

Section A - Accident Details

Registration Number	SHF107A
Case Reference Number	TAX/12/24/2009
Registration Date	26/Dec/2019
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN CHUNG (CHEN ZHONG) @ MOHAMAD RAZIZ BIN ABDULLAH
Type of Accident	Side Swipe
Accident Date and Time	3/Dec/2024 3:05 PM
Accident Reported Date and Time	3/Dec/2024 4:04 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120011
Special Instruction to ARC, if any	TP
Prepared Date and Time	3/Dec/2024 6:56 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$300.00
Total Spray Cost	\$2,172.00	\$950.00
Total Spare Part Cost	\$9,689.98	\$905.29
Total Other Cost	\$620.00	\$100.00
TOTAL COST	\$13,833.98	\$2,255.29
Lump Sum Total	\$13,850.00	\$2,250.00 (L/S)
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	Mun San #	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	04/12/2024 8:33 PM	04/12/2024 4:42 PM
Signature		
Remarks	Expected length of repair (days) = 3 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 10-12-2024 L/S REPAIR / AFTER PAINT PHOTO . FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR STEVE CHEN (LKK) / HP : 010-9429 541 / Email : stevechen@kkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	E24120022	Invoice Number	
Quotation Date	3/12/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,352.00	\$300.00
Total Labour	\$1,352.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$220.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$100.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY RIM	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$2,172.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$620.00	\$100.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		42611-47450	WHEEL, DISC FRONT	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given
		53875-47120	LINER, FR FENDER, RH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given
		53801-47080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace

X
R
X
X
√

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/12/2024

User ID : PohSuan

	51443-12110	COVER, ENGINE UNDER SIDE RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
	42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Replace	√
	43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Not Given	X
	43211-47040	KNUCKLE, STEERING, RH	0.00	\$717.50	0.00	\$0.00	Replace	Not Given	X
	48068-47060	LOWER ARM SUB-ASSY, FRONT RH	0.00	\$823.20	0.00	\$0.00	Replace	Not Given	X
	87910-47450	MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1,556.00	0.00	\$0.00	Replace	Not Given	X
	87915-47070-A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	100.00	\$0.00	Replace	Repair	R
	67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
	69210-47041-A1	DOOR OUTER HANDLE FRONT , RH	0.00	\$423.20	0.00	\$0.00	Replace	Not Given	X
	68710-12151	HINGE ASSY, FRONT DOOR , UPPER RH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
	68730-12120	HINGE ASSY, FRONT DOOR , LOWER RH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X
		STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
	67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
	68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
	68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X
	68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X
		STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
	52119-47980	COVER, FR BUMPER	1.00	\$565.60	100.00	\$0.00	Replace	Repair	R
	52115-47050	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	52161-16010	CLIPS PIECE, RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$103.70	0.00	\$0.00	Replace	Not Given	X
	81145-47890	UNIT , HEADLAMP , RH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given	X
Total				\$16,066.70		\$1,131.61			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,131.61
 -20% L/S \$2,250/-

 905.29
 + 300.00
 + 1050.00

 2,255.29