



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

MUHAMMAD ZAHARI BIN TAJUDIN
1 Corporation Drive,
#04-05 REVV @ Corporation Drive,
Singapore 619775.

TP
Date 3/12/2024
No of Page : 1/1

Registration No : SJL 584A

Model : Honda CrossRoad 1.8A

Accident Date : 1-Dec-24

Chassis No: RT11007872

Our Ref : TP

Engine Capacity : 1799

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Door RHS	\$ 1,252.50	\$ 1,252.50
2	1	Rear Door arc garnish RHS	\$ 581.80	\$ 581.80
3	1	Rear Fender Wheel Arc Garnish RHS	\$ 365.70	\$ 365.70
4	1	Rear Bumper	\$ 865.70	\$ 865.70
				\$ 3,065.70
				-20% \$ 613.14
Total for spare parts				\$ 2,452.56

947.50
258

Special Nett

1	1 set	arc garnish fastener clips	\$ 50.00	\$ 50.00
2	1pc	Rear Rim RHS	\$ 800.00	\$ 800.00
				\$ 850.00
Sub-Total for Parts :				\$ 3,302.56

20

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		300 500.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		400 500.00
3		to perform wheel alignment		✓ 80.00
4		To check wiring system to facilitate repair and refit the same		nn x 80.00
5		Apply rust proofing on the adjacent panels		810 30 80.00
TOTAL AMOUNT :				1,240.00
OVERALL COST :				4,542.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjik 9749 97495749 / 62563561
WP 4/12/24 e 215 pm
L/S Resurvey after repair
- 3 days
Tanjik@lkkauto.com

758
20
810
1588
11581250
- 3 days
*