

CD | FC124120051 | Tpa3

COE-2028/11

Veh No: 556584A Yr Regn: 2008, 11

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Crossroad cc 1799

Colour: Light A/C: Insured / 3rd / NI / NA

Sp. Reading 171085 T/Prior: Insured / 364 / NI / NA

Eng/No: _____

CAN: RT1100 7872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: Inducer / Jammed / Leaked / Burnt or

Modl: NII / 12m / STD A/B/m or

N/S	O/S

BS/DUN/EYNMA/GY/ES/11ZA/MIC/CHTSII/PIR/SIM/

Front Rear

R/Bal. mm R/Bal. mm

U8al. mm U8al. mm

D.O.A. D.O.L. 4/12/24

Survey held at RGC Workshop

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Roof/Top or

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 0 5 6

The U/C / Chassis frame / Body Structure affected due to collision.

TOTAL



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

MUHAMMAD ZAHARI BIN TAJUDIN
1 Corporation Drive,
#04-05 REVV @ Corporation Drive,
Singapore 619775.

TP
Date 3/12/2024
No of Page : 1/1

Registration No : SJL 584A

Model : Honda CrossRoad 1.8A

Accident Date : 1-Dec-24

Chassis No: RT11007872

Our Ref : TP

Engine Capacity : 1799

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Door RHS	\$ 1,252.50	\$ <i>RT</i> 1,252.50
2	1	Rear Door arc garnish RHS	\$ 581.80	\$ <i>cut</i> 581.80
3	1	Rear Fender Wheel Arc Garnish RHS	\$ 365.70	\$ <i>cut</i> 365.70
4	1	Rear Bumper	\$ 865.70	\$ <i>Rx</i> 865.70
				\$ 3,065.70
			-20%	\$ 613.14
Total for spare parts				\$ 2,452.56

Special Nett

1	1 set	arc garnish fastener clips	\$ 50.00	\$ <i>20%</i> 50.00
2	1pc	Rear Rim RHS	\$ 800.00	\$ <i>xR</i> 800.00
				\$ 850.00
Sub-Total for Parts :				\$ 3,302.56

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		<i>300</i> 500.00
2		To putty and spray paint on all accident damage parts and other accident affected areas		<i>400</i> 500.00
3		to perform wheel alignment		<i>✓</i> 80.00
4		To check wiring system to facilitate repair and refit the same		<i>x</i> 80.00
5		Apply rust proofing on the adjacent panels		<i>30</i> 80.00
TOTAL AMOUNT :				1,240.00
OVERALL COST :				4,542.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjik 9749 97495749 / 62563561
WP 4/12/24 @ 2:15 PM
L/S Resurvey after repair
- 3 days
Tanjik@lkkauto.com