

REF:

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SFP 28R

Yr Regn: _____

2024 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

BYD Denza Elite c.d

Colour: _____

Black

A/C: Insured / Std / NI / NA

Sp. Reading: _____

559.

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

LCODE4CDIRO485244

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

235/60R18

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.A. _____

05/12/24

Survey held at _____

1st Automatic

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP All

COE Expiry: _____

Estimate given during: Yes ()

1st Survey: No ()

MV: _____

PV: _____

Nett: _____

Date/Time, File Pass to?



Prel. Report

Days Of Repair: _____

1)



Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: _____



Site Insp (\$



Interview (\$



Tech. Inve (\$

Survey Fee: _____

Transportation: _____

3 + R.S. \$1

Photos

Others

Report Forwarded: _____

Signature of Insurer: _____

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 4/12/2024

Reference: SFP28R
BYD / DENZA
Make: D9 ELITE

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SFP28R
CHASSIS NO.: LC0DE4CD1R0485244

Name of insured : Tan Khai Leng
Date of accident : 02/12/2024

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Tailgate <i>Dented</i>	\$ 2,400.00
2	1	Rear Tailgate Weatherstrip Seal	\$ 70.00
3	1	Rear Tailgate Upper Weatherstrip Seal <i>HP</i>	\$ 15.00
4	1	Rear Tailgate Lock Assy <i>HP</i>	\$ 140.00
5	1	Rear Tailgate Striker <i>HP</i>	\$ 25.00
6	1	Denza Lettering <i>HP</i>	\$ 20.00
7	1	Denza D9 Lettering <i>HP</i>	\$ 15.00
8	1	EV Lettering <i>HP</i>	\$ 10.00
9	1	Rear Bumper Upper Sill Guard <i>HP</i>	\$ 50.00
10	1	Rear Bumper Right Sill Guard <i>HP</i>	\$ 40.00
11	1	Rear Bumper Left Sill Guard <i>HP</i>	\$ 40.00
12	1	Rear Bumper <i>HP</i>	\$ 350.00
13	1	Rear Windscreen with Moulding <i>HP</i>	\$ 360.00
14	10	Rear Tailgate Inner Trim Board Clips <i>HP</i>	\$ 50.00

Parts Total: \$ 3,585.00
Cost plus 10%: \$ 358.50
Total : \$ 3,943.50

Labour

No.	Labour Description	Price (SGD)
1	<u>Rear portion</u> To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$600 PER DAY)	\$ 2,400.00

<u>2</u>	Carry out spray painting on accident affected area (\$600 PER PANEL)	\$ 2,400.00	1200
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 600.00	100
<u>4</u>	To remove and refix reverse camera and conduct test	\$ 200.00	100
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 200.00	100
<u>6</u>	To remove and replace rear windscreen with moulding	\$ 200.00	✓
<u>7</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 200.00	150
<u>8</u>	To conduct water leakage test after repairs of vehicle	\$ 200.00	x

Labour Total : \$ 6,400.00

Others

Other Description

<u>No.</u>	<u>Qty</u>	<u>Price (SGD)</u>
<u>Rear portion</u>		
1	1	NA

Other Total: \$ -

Total: \$ 10,343.50
GST 9%: \$ 930.92
GRAND TOTAL: \$ 11,274.42

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully




Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adm Lj
P/P 05/12/24

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: