

ASS. REC. BY:

REF:

1051

CS

10524120053

Knh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop nvs

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 3731E

Yr Regn:

11, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c.

1998

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

345064

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FD 2

120 3283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

BS

245/40R17

R:

DM

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

4

mm

L/Bal.

6

mm

L/Bal.

4

mm

D.O.A.

28/11/24

D.O.I.

4/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015PM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

EN not ready

9/12 11:28 32501 Coker (Red, \$ 3899.40, 547.)

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

4

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

NOT Authorized
1/12/24 @ 3250h
Running After Repair
4 days

Vehicle Number : SLF 3731E

Date: 28.11.24

S/N Parts Description

Unit Price Amt

- 1 Front fender RH
- 2 Front fender inner shield RH
- 3 Front fender inner shield clips RH
- 4 Headlamp RH
- 5 Headlamp bracket RH
- 6 Front grille
- 7 Front grille clips
- 8 Front bumper assy
- 9 Front bumper retainer X 2
- 9 Front bumper lower grille
- 10 Front bumper lower cover
- 11 Front bumper reinforcement

R \$837.60 X
Ta \$191.80 ✓
M \$60.00 ✓
M/cm \$1,100.00 ✓
DIT \$79.90 ✓
M/cm \$401.50 ✓
M \$50.00 ✓
Bul/ M/cm \$1,101.40 ✓
\$68.00 DIT \$136.00 ✓
Su \$187.00 X
R \$138.20 X
R \$386.00 X

201

4669.40

Special Nett

- 1 Front bumper clips
- 2 Front No. plate
- 3 Front bumper lower spoiler

M \$50.00 ✓
Su \$60.00 X
Cm \$600.00 ✓

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas.
- 2 To spray paint on affected areas.
- 3 Check wiring
- 4 Tuff coating

\$800.00 400l
\$800.00 600l
\$50.00 20l
na \$120.00 X

\$1,770.00

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7149.4

\$1,770.00