

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

NOT Notified
1/12/2018 & 3250h
Running After Rain
4 days

Vehicle Number : SLF 3731E

Date: 28.11.24

S/N Parts Description

Unit Price Amt

- 1 Front fender RH
- 2 Front fender inner shield RH
- 3 Front fender inner shield clips RH
- 4 Headlamp RH
- 5 Headlamp bracket RH
- 6 Front grille
- 7 Front grille clips
- 8 Front bumper assy
- 9 Front bumper retainer X 2
- 9 Front bumper lower grille
- 10 Front bumper lower cover
- 11 Front bumper reinforcement

R \$837.60 X
Ta \$191.80 ✓
M \$60.00 ✓
mgem \$1,100.00 ✓
DIT \$79.90 ✓
mgem \$401.50 ✓
M \$50.00 ✓
Brel mgem \$1,101.40 ✓
\$68.00 DIT \$136.00 ✓
Su \$187.00 X
R \$138.20 X
R \$386.00 X

Special Nett

- 1 Front bumper clips
- 2 Front No. plate
- 3 Front bumper lower spoiler

M \$50.00 ✓
Su \$60.00 X
cm \$600.00 ✓

20%

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas.
- 2 To spray paint on affected areas.
- 3 Check wiring
- 4 Tuff coating

\$800.00 400l
\$800.00 600l
\$50.00 20l
na \$120.00 X

\$1,770.00

Page 1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: