

PLEASE ARRANGE TO SURVEY
VEHICLE AT PANDAN ROAD

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 04/12/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 26/11/2024

Vehicle No : GBH-9042-D

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR FENDER RH	RESTORE Rp	
1	TAILLAMP RH	290.00	ana ✓
1	TAILLAMP LOWER PANEL RH	124.50	de ✓
1	REAR BUMPER	RESTORE Rp	
Sub Total		414.50	414.50
Discount 25% On Parts		(103.63)	310.87
<u>Special Nett Item</u>			
1	ADVERTISMENT STICKER	300.00	nel ✓

Parts - \$310.87
stnet - \$300.00
Labour - \$960.00
\$1570.87

Date : 04/12/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 26/11/2024

Vehicle No : GBH-9042-D Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	300.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	600.00	400
	TO RESPRAY AFFECTED AREAS	600.00	500
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	1
	RUST PROOFING	50.00	30
	Sub Total	1280.00	
			960
		1,890.88	

Remarks:

SUB TOTAL

GST 9.0 % 170.18

TOTAL 2,061.05

Surveyor's name:

Tanfer 9749544

Principal's name: ETHOZ Group Ltd

p/p Resumy new parts.

Survey Date & Time:

WP' 4/12/24 430pm 04 days

310.87

300

960

\$1570.87

4 DAYS #