



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBH 9042D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	TAILLAMP RH	CRACKED	\$290.00	\$290.00
1	TAILLAMP LOWER PANEL RH	DEFORMED	\$124.50	\$124.50
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 25.00% DISCOUNT		(\$103.63)	(\$103.63)
			\$310.87	\$310.87
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	ADVERTISEMENT STICKER (SN)	NECESSARY	\$300.00	\$300.00
			\$300.00	\$300.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR BUMPER		\$600.00	\$400.00
	TO RESPRAY AFFECTED AREAS		\$600.00	\$500.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS		\$30.00	\$30.00
	RUST PROOFING		\$50.00	\$30.00
			\$1,280.00	\$960.00
GRAND TOTAL			\$1,890.87	\$1,570.87
RECOMMENDED COST OF REPAIRS				\$1,570.87
Report Ref No: CS/TP24120055/Tnh3e2				

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.