

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : GBM 2791 U

CHASSIS NO : VR7EAKXZNJ863075

MAKE / MODEL : CITROEN BERLINGO

ACCIDENT DATE : 02.12.2024

Huikang
TP INC

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Front RH door <i>Dented</i>	1	\$ 3129.26
2	Front RH door glass <i>Cut</i>	1	\$ 1116.82
3	Front RH door glass outer moulding <i>Cut</i>	1	\$ 315.61
4	Front RH door protactor <i>Cut</i>	1	\$ 657.11
5	Front RH door quater glass <i>Shattered</i>	1	\$ 669.18
6	Front RH door quater glass moulding <i>new</i>	1	\$ 312.51
7	Front RH door glass frame <i>Cut</i>	1	\$ 426.99
8	Front RH door side mirror assy <i>Distorted</i>	1	\$ 1399.66
9	Front RH door sun vision <i>new</i>	1	\$ 138.00
10	Front RH door company sticker <i>new</i>	1	\$ 23.00
11	Front RH door top hinge	1	\$ 312.51
12	Front RH door lower hinge	1	\$ 311.76
13	Front RH door stopper	1	\$ 321.88
14	Front RH door side mirror inner cover <i>Damaged</i>	1	\$ 840.76
15	Front RH door inner board <i>Cracked</i>	1	\$ 1968.91
16	Front RH fender <i>Dented</i>	1	\$ 1117.22
17	Front RH fender signal lamp <i>3rd</i>	1	\$ 427.51
18	Front RH fender quater garnish	1	\$ 346.38
19	Front RH fender inner shield <i>horn</i>	1	\$ 312.51
20	Front RH fender inner shield clips <i>new</i>	1	\$ 5.06
21	Front bumper <i>cracked</i>	1	\$ 1969.03
22	Front bumper side holder @ \$312.11 <i>RH side</i>	2	\$ 624.22
23	Front bumper RH fod lamp <i>cracked</i>	1	\$ 428.03
24	Front bumper RH fod lamp cover <i>new</i>	1	\$ 312.45
25	Front bumper clips <i>new</i>	1	\$ 5.06
26	Front RH headlamp <i>Cut</i>	1	\$ 1213.72
27	Company advertisement <i>new</i>	1	\$ 460.00
28	Front RH door pillar <i>Repair</i>	1	\$ 841.68
29	Front door glass solar flim <i>new</i>	2	\$ 345.00
30	Front bumper top aprom cover <i>new</i>	1	\$ 427.97
31	Front engine lower cover <i>horn</i>	1	\$ 657.45
			\$ 20537.25
			\$ 2053.725
			\$ 18483.53

Front Door Quarter Glass Solar Film
200 150
new

LESS 10 % DISC

TOTAL

2513
790
168
95
420
750
109
125
1420
2150
345
300
150
7
410

14062.51

12656.25

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : GBM 2791 U

CHASSIS NO : VR7EAKXZNJ863075

MAKE / MODEL : CITROEN BERLINGO

ACCIDENT DATE : 02.12.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LABOUR COST			
1	Remove + reinstall door glass	1	\$ 150.00
2	Remove , replace + repair consistent to the accident	1	\$ 1500.00
3	Respray painting	1	\$ 1200.00
4	Tuff kote	1	\$ 100.00
5	Remove + reinstall sensor	1	\$ 150.00
TOTAL			\$ 3100.00
GRAND TOTAL			\$ 21583.53

1750

Adrian Cj
L/S 04/12/24.

08 Days.

total: 14406.25

L/S: 11.5K

11.5K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: