

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/Fc124120060/unh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBM74435at Workshop m/s 801 Smith

of _____

Insured: SH 78174

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$120k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**C 8416

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

L1A 74081Veh No: GBM74435 Yr Regn: 22/10/24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or carMake: Toyota hiace c.c. 2755Colour: White A/C: Insured / Std / NI / NASp. Reading: 4848 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ITFHA02P508005505Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**TOYO / YOKO** orFront: 8 mm Rear: 8 mmR/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 2/12/24 D.O.I. 5/12/24

Survey held at _____

Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop orRear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13k.9/12/24 2/5 \$2400 in hand Alex (Red, \$13119.83, 84%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	841H
Vehicle Details	
Vehicle No.:	GBM7443S
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR AT
Primary Colour:	White
Manufacturing Year:	2024
Engine No.:	1GD9392355
Chassis No.:	JTFHA02P508005505
Maximum Power Output:	-
Open Market Value:	\$30,770.00
Original Registration Date:	22 Oct 2024
First Registration Date:	22 Oct 2024
Transfer Count:	0
Actual ARF Paid:	\$1,539.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2034
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$75,009.00
COE Rebate Amount:	\$74,081.00
Total Rebate Amount:	\$74,081.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 05 Dec 2024

OK



PREMIUM AD

Toyota Hiace Commuter 2.8A GL **\$144,800** \$15,000 /yr 30-Jul-2024 (9yrs 7mths COE left) 18 km 2,754 cc

Instl. \$1,908 /mth 1 Owner Diesel

Newly ready to register, fresh from Japan stocks. Guaranteed specs with no gimmicks, bank loan and in house welcomed. Trade in welcomed. Immediate stocks with full cash welcomed. Contact for more information.

SG Motor Link Pte Ltd|Posted 04-Dec-2024

☐ Compare



PREMIUM AD

Toyota Hiace Commuter 2.8A GL High Roof **\$137,888** \$14,090 /yr 18-Sep-2024 (9yrs 9mths COE left) 18 km 2,754 cc 1 Owner Diesel

Instl. \$1,817 /mth

Latest unit, highest spec PI commuter mini bus in market. Numbers don't lie. full price breakdown before confirmation, immediate viewing with bank loan and in house available. full cash possible as well. Loan less able to nego as well

SG Motor Link Pte Ltd|Posted 04-Dec-2024

☐ Compare



PREMIUM AD

Toyota Hiace 2.8A **\$131,813** \$13,420 /yr 30-Sep-2024 (9yrs 9mths COE left) N.A. 2,755 cc 1 Owner

Instl. \$1,737 /mth Diesel

Ready stock, Toyota Hiace 2.8 auto diesel unit 5 doors, Borneo Motors unit, immediate stock, 100% loan welcome, no additional cost, all in price! Borneo servicing and warranty, call now, all trade in welcome.

1F Motoring Pte Ltd|Posted 03-Dec-2024

☐ Compare



PREMIUM AD

Toyota Hiace 2.8A **\$129,800** \$13,170 /yr 11-Oct-2024 (9yrs 10mths COE left) N.A. 2,755 cc 1 Owner

Instl. \$1,710 /mth Diesel

Lek Auto Pte Ltd|Posted 03-Dec-2024

☐ Compare



PREMIUM AD

Toyota Hiace Commuter 2.8A GL High Roof **\$136,800** \$14,580 /yr 23-Apr-2024 (9yrs 4mths COE left) N.A. 2,754 cc 1 Owner Diesel

Instl. \$1,802 /mth

All new PI Toyota hi roof combi 13+1 seaters! PZ/PB/PH/CB plate. 100% loan available. Call us now for viewing appointment!

Ezy-1 Pte Ltd|Posted 03-Dec-2024

☐ Compare

Compare

CARSMITH PRIVATE LIMITED

PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: GBM7443S

MAKE & MODEL: TOYOTA HIACE

DOA: 02.12.2024

CLAIM TYPE: TP CLAIM

Not Authorized
Mey
5/12/24

4 days.
1/5 @ 2400
take photo. After repair

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 2,598.00	R X
TAILGATE RUBBER TOP GARNISH	1	\$ 254.00	11 X
TAILGATE RUBBER	1	\$ 328.50	11 X
TAILGATE LOCK	1	\$ 285.10	11 X
TAILGATE HINGE	2	\$ 190.50	11 X
TAILGATE ABSORBER	2	\$ 590.00	11 X
TAILGATE CENTER GARNISH	1	\$ 186.50	11 X
TAILGATE HANDLE	1	\$ 255.00	11 X
TAILGATE INNER BOARD	1	\$ 335.20	11 X
TAILGATE LOCK ACTUATOR	1	\$ 430.60	11 X
TAILGATE EMBLEM LOGO	1	\$ 108.00	new 98-10
TAILGATE WINDSCREEN MOULDING	1	\$ 218.50	NS X
TAILGATE WINDSCREEN	1	\$ 1,250.00	11 X
TAILGATE STOPPER	2	\$ 80.00	11 X
REAR END PANEL INNER	1	\$ 912.70	R X
REAR END PANEL OUTER	1	\$ 486.50	20
REAR FLOOR BOARD PANEL	1	\$ 2,381.40	11 X
INNER BUMPER PLATE	1	\$ 325.00	NF X
REAR LAMP left 2H	1	\$ 640.00	11 X
REAR LAMP right 2H	1	\$ 640.00	20/30H
REAR BUMPER	1	\$ 698.00	20/30H
REAR BUMPER SIDE RETAINER	2	\$ 161.60	11 X
REAR BUMPER LOWER SUPPORT BRACKET	4	\$ 244.80	50 X

\$ 13,599.90

LESS 25% \$ 3,399.98

SUB TOTAL \$ 10,199.93

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	new 30 S/N
REAR NUMBER PLATE	1 SET	\$ 80.00	11 X
TAILGATE STICKER '70KM/H' 8'8 29x'	1	\$ 45.00	new 20 S/N
TAILGATE STICKER 'HIACE'	1	\$ 45.00	new S/N
REVERSE SENSOR	1 SET	\$ 480.00	malfunction 200 S/N
REVERSE CAMERA	1 SET	\$ 480.00	11 X
JOINT SEALANT	1	\$ 120.00	11 X

SUB TOTAL \$ 1,300.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	11 X

PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	600
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,600.00	600
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	30

SUB TOTAL \$ 4,020.00

GRAND TOTAL \$ 15,519.93

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1922-6
252
P-1441-95
S.W-298
L-1280
3016-95
202
2413