



CARWORKZ SG PTE LTD
10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645
H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua)
Co. Reg. No: 202039874Z GST No: 202039874Z
Email: carworkzsg@gmail.com

ESTIMATED REPAIR COST DETAILS

ACC-24-0089
Date: 04/12/2024
Vehicle No.: SLB-5197-E
Make: FORD
Model: FOCUS HB TREND 1.6
TI-VCT A/T 5DR
Not Authorised
61km @ 2300h
Running After Rain
2 days

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPER	1980	my cm \$2,075.00	✓
15	REAR BUMPER CLIPS		my \$150.00	50in
1	REAR BUMPER RETAINER LH		my \$135.00	✓
1	REAR BUMPER RETAINER RH		my \$135.00	✓
1	REAR BUMPER BRACKET LH		my \$145.00	✓
1	REAR BUMPER BRACKET RH		my \$145.00	✓
1	REAR BUMPER REFLECTOR RH		my \$180.00	✓
1	REAR BUMPER LOWER GARNISH	550	my \$750.00	✓
6	REAR BUMPER LOWER GARNISH CLIPS		my \$60.00	30in
1	REAR BUMPER LOWER GARNISH BRACKET LH		my \$48.00	✓
1	REAR BUMPER LOWER GARNISH BRACKET RH		my \$48.00	✓
2	REAR BUMPER REVERSE SENSOR (ORI)		my \$640.00	✓
1	REAR BUMPER INNER CENTRE BRACKET		my \$185.00	✓
1	REAR BUMPER REINFORCEMENT		my \$678.00	✓
1	END PANEL		my \$835.00	✓
1	END PANEL TOP GARNISH		my \$415.00	✓
6	END PANEL TOP GARNISH CLIPS		my \$60.00	✓
Sub Total			\$6,684.00	
Discount 20% on Parts			(\$1,336.80)	
Sub Total			\$5,347.20	
Special Nett			\$60.00	✓
1 END PANEL SEALANT			\$60.00	✓
Sub Total			\$60.00	

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:



CARWORKZ SG PTE LTD
10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645
H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua)
Co. Reg. No: 202039874Z GST No: 202039874Z
Email: carworkzsg@gmail.com

ESTIMATED REPAIR COST DETAILS

ACC-24-0089

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$800.00	2001
R & R REAR FENDER INNER TRIMS LH & RH	\$280.00	X
R & R SPARE TYRE COMPARTMENT TRIMS	\$180.00	X
R & R REVERSE SENSOR	\$60.00	501
CHECK & RECONNECT WIRINGS	\$60.00	151
TO RUST PROOF AFFECTED AREA	\$80.00	X
LABOUR TO SPRAY PAINT AFFECTED AREAS	\$600.00	2101
Sub Total	\$2,060.00	

Sub Total	\$7,467.20
GST 9%	\$672.05
Total	\$8,139.25