

ASS. REC. BY:

REF:

C9/ AG 24120062/Kgh3

G

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Evt not ready

9/12 85700k Cghw (Red \$ 8033.40, 58%)

Date/Time, File Pass to?

1) 05/12 12:00

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP 5700

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMK 2817K

Date: 29.11.24

NOT Authorized
1/1mp @ 5700h
Pickup After Paint
5 days

S/N Parts Description

Unit Price Amt

- 1 Front fender RH
- 2 Front fender inner shield RH
- 3 Front fender inner shield clips RH
- 4 Headlamp RH
- 5 Headlamp bracket RH
- 6 Front grille
- 7 Front grille clips
- 8 Front bumper assy
- 9 Front bumper retainer X 2
- 9 Front bumper fog lamp
- 10 Front bumper fog lamp cover
- 11 Front door mirror RH
- 12 Front door outer mldg RH
- 13 Front side glass with mldg
- 14 Front wheel rim RH
- 15 Front knuckle RH
- 16 Front knuckle bearing RH
- 17 Front shock absorber RH
- 18 Front lower arm RH
- 19 Front stay bar RH

R \$895.50 X
Sm \$176.40 X
na \$60.00 X
Gr \$2,433.60 ✓
CM \$95.00 ✓
Sm \$695.00 X
na \$40.00 X
M/C \$869.00 ✓
o/s \$45.20 \$90.40 ✓
Sm \$387.10 X
Sm \$106.20 X
7m/CM \$1,068.20 ✓
na \$95.20 ✓
mtg \$380.60 ✓
na \$938.70 ✓
By \$518.20 ✓
na \$270.40 ✓
Sm \$510.70 X
o/s \$531.40 ✓
Sm \$121.80 X

Special Nett

- 1 Front bumper clips
- 2 Front No. plate
- 3 Front fender clips
- 4 Front tyre RH
- 5 Front side glass sealant RH

na \$50.00 ✓
Sm \$60.00 X
na \$80.00 X
Sm \$320.00 X
na \$80.00 308h

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas.
- 2 To spray paint on affected areas.
- 3 Check wiring
- 4 Tuff coating
- 5 To conduct wheel alignment

\$1,000.00 500h
 \$1,200.00 500h
 \$50.00 20h
 \$120.00 X
 \$120.00 60h

20h

6 To renew front side glass

\$120.00 50/-

To remove & renew under carriage parts

\$2,610.00

\$ 250.00 160/-

Page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: