

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO24120064/Uqh3e2	
	50 RAFFLES PLAC	E #03-03 TOWER SINGAPORE 048623	Date:	27/12/2024	
	SINGAP ORE LAND	TOWER SINGAL ONE 040023	Code:	SMO	
1.	1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	FBG 4039C	Veh. Inspected	SLD 3425A	
	Policy No.	-	Coverage	0	
	Claim No.	CMTD2403921/JYC	Excess	\$0.00	
	Assign From	IRENE HENRY	Assign Date	05/12/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL HYBRID	C.C	1496	
	Engine No.	LEB5903790	Year of Reg.	14/06/2016	
	Chassis No.	RU31203780	Colour	BLACK	
	Odometer	174190 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R16	KUMHO	6	
	L/H Front Tyre	215/60R16	KUMHO	6	
	R/H Rear Tyre	215/60R16	KUMHO	6	
	L/H Rear Tyre	215/60R16	KUMHO	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
5.	General Information				
	Accident Date	04/12/2024	Inspection Date	05/12/2024 (14:02)	
	Survey held at	JHK AUTO SERVICES - 3014 UBI RO	AD 1 #01-322 SING	SAPORE 408702	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.					
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.					
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,800					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

CKS

MARCUS CHUA KANG SENG Licensed Appraiser