



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: TEO SWEE KEONG			Ref: CS/FCI24120065/Avh3e2(N) Date: 16/06/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8200L	Veh. Inspected	SLK 2558U	
Policy No.	D-24101860MFCT	Coverage (\$)	0.00	
Claim No.	D24010602MFCT	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	05/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11213291	Colour	RED	
Odometer	287997 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2024	Inspection Date	06/12/2024	
Survey held at	KIM SIA AUTO SERVICE 2 KAKI BUKIT AVENUE 2 #02-21 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	