

KIM SIA AUTO SERVICE

No. 2 KAKI BUKIT AVENUE

63H/P: 84843837 (AH LONG)

Vehicle No: SLK2558U

Model & Make : HONDA VEZEL 1.5X CVT

TP 1st Cap

Veron

Vehicle Parts

Rear Portion

Rear Tailgate Comp	Dented	1181.57	1100
Tailgate Rubber Seal	lt	139.77	
Tailgate Trim Board Assy	Crackd.	349.09	
Centre Backdoor Garnish	new	158.13	
Tailgate Hinge (L & R)	new	172.06	
Rear Bumper	Deformed	952.92	745
Rear Bumper Retainer (L & R)	new	76.28	
Rear Bumper Extension (L & R)	torn	113.52	
License Plate Lamp Assy	new	77.90	
Rear Wiper Motor Assy	new	587.47	
Tailgate Lock Assy	Dented	250.00	
Tailgate Opener Switch Assy	new	143.44	
Tailgate Dampers (L & R)	new	234.00	
Tailgate Lock Striker Assy	new	29.53	
Tailgate Dynamic Damper	new	78.59	
Rear Lamp Assy (L & R)	new	1,382.70	
Rear Combination Lamp Assy (L & R)	new	1,697.17	
Rear Reflector Assy (L & R)	LH Crackd	62.22	31.11
Rear Wheel Arch Protector (L & R)	LH Deformed	375.62	187.81

Rear Portion Gross Total

\$8,061.98

Less : 20%

\$1,612.40

Rear Portion Net Total

\$6,449.58

Special Nett Items

Rear Bumper Cover Rivet(s)	new	90.00	
Rear Bumper Cover Screw(s)	new	45.00	30
Rear Bumper Bolt(s)	new	26.00	
Rear Bumper Nut(s)	new	26.00	
Rear Tailgate Bolt(s)	new	39.00	
Rear Tailgate Nut(s)	new	35.00	
Rear Tailgate Trimboard Clip(s)	new	30.00	
Rear Diffuser (Aftermarket)	Crackd	120.00	
Tail Lamp Nut(s)	new	35.00	
Rear License Plate	new	80.00	
Rear License Plate Cover	new	40.00	
Rear Reverse Sensor (2 point)	Dented	120.00	

Special Nett Item Total

\$686.00

Labour

ELECTRICAL MISCELLANEOUS

(ECU) To remove tailgate glass	200.00	120
To Rectify & Remove and/or Replace Damaged Wiring	200.00	30

