



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

not allowed
no way
1/7/24
d/s = 6000
The phl. Hb my...
90096608
Hlys

Date :

Total Pages :

TO: Whom it may concern

Our Customer : Global Advance Leasing

Vehicle No : **SMR7375Z**

Model : Toyota Voxy

Manufacture Year : 2019

Date of Accident : 26/5/2024

Total Estimate Repair Days :

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front Bumper 1680.00	1	\$2,381.10	\$2,381.10	Del/Born ✓
2	Front Bumper Clips	12	\$5.50	\$66.00	Per 305/w ✓
3	Front Bumper Side Retainer	2	\$154.20	\$304.40	11 X
4	Front Bumper Lower Grille	1	\$284.90	\$284.90	11 X
5	Front Radiator Grille	1	\$1,115.00	\$1,115.00	one ✓
6	Front Radiator Grille Outer Garnish > complete	1			
7	Front Radiator Grille Clips	4	\$5.50	\$22.00	11 X
8	Bonnet	1	\$1,182.90	\$1,182.90	20/Bent ✓
9	Bonnet Hinge	2	\$86.40	\$172.80	11 X
10	Bonnet Lock	1	\$127.70	\$127.70	5m X
11	Bonnet Insulator Clip	5	\$5.50	\$27.50	11 X
12	Bonnet Outer Chrome Garnish	1	\$358.40	\$358.40	one ✓
13	Bonnet Emblem	1	\$116.20	\$116.20	5m ✓
14	Support Panel 1866.10	1	\$2,394.90	\$2,394.90	Bent ✓
15	Brace Panel	1	\$126.90	\$126.90	7m ✓
16	Aircon Condenser	1	\$1,839.30	\$1,839.30	Bent / par ✓
17	Aircon Condenser Air Guide	2	\$69.40	\$138.80	11 X
18	Radiator Assy	1	\$3,102.70	\$3,102.70	11 X
19	Radiator Spare Tank	1	\$258.30	\$258.30	11 X
20	Radiator Fan Cowling	1	\$403.10	\$403.10	11 X
21	Radiator Motor	1	\$963.60	\$963.60	11 X
22	Radiator Blade	1	\$244.90	\$244.90	11 X
23	Aircon Fan Motor	1	\$963.60	\$963.60	11 X
24	Aircon Fan Blade	1	\$329.80	\$329.80	11 X
	Sub Total			\$16,924.80	
	Less 20%			\$3,384.96	
	Sub Total 1			\$13,539.84	
B.	Special Nett				
1	Front Sensor	4	\$250.00	\$250.00	AT X
	front number plate \$500/2 km				
	Sub Total 2			\$250.00	
	35 S/W				
C	Labour				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$1,320.00	550
2	To top up aircon gas			\$120.00	100
3	To replace radiator			\$80.00	11 X
4	To check all necessary lighting and wiring			\$120.00	20



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

5	To spray paint the affected areas	\$900.00	600
6	To rust proof all affected areas	\$60.00	30
Total Labour		\$2,600.00	
Total Repair Cost		\$16,389.84	
* The above quoted are exclusive of GST.			

Yours faithfully,

Kai
f KT Garage Pte Ltd

Surveyor's Details	
Name	Wong
Contact	90086608
Survey Date	1/7/24
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	[Signature]

NOT Authorize
1/7/24 \$6000
4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P-8284.80
242
P-6213.60
S.W-35
L-1300
7548.60
202
6038.