



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

ATTN : ACCOUNTS DEPT

FAX :

Not Authorised
Refusing 34 painting
4 days
\$ 4154.20

ESTIMATE

NO : QUOT202412-000009(00)

DATE : 04/12/2024

POLICY NO : SP2003907937

VEH REG NO : SMU9537U

MAKE/MODEL : MERCEDES BENZ A200
SALOON PROGRESSIVE (R18
LED)

CHASSIS NO : W1K1771872J239539

ENGINE NO : 28291480402483

REG. DATE : 2020

YOUR REF NO : GBH8053D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 15/11/2024

TP VEH REG NO : GBH8053D

Estimate Repair Cost to Vehicle No : SMU9537U

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Bootlid	1	3,190.00	3,190.00 X
2 Bootlid 'A200' emblem	1	168.00	168.00
3 Bootlid centre logo	1	73.00	73.00
4 Bootlid weatherstrip	1	236.00	236.00 X
5 Rear end panel	1	1,298.00	1,298.00 X
6 Rear end panel top garnish	1	102.00	102.00 X
7 Rear bumper	1	1,625.00	1,625.00
8 Rear bumper reinforcement	1	605.00	605.00
9 Rear bumper inner frame	1	108.00	108.00
10 Rear bumper sensor	2	216.00	432.00 X
11 Rear bumper sensor seals	6	12.00	72.00
12 Rear bumper clips	15	10.00	150.00 60.00
13 Rear bumper lower garnish	1	595.00	595.00
14 Rear bumper centre chrome	1	350.00	350.00
			9,004.00
		Less 10%	896.80
			8,107.20
SPECIAL NET			
15 Bootlid 'C&C' emblem	1	40.00	40.00
			40.00
LABOUR			
16 To transfer damaged bootlid interior mechanism to new bootlid	1	120.00	120.00 X
17 To check & rectify wiring system	1	80.00	80.00 151
18 To remove & refit rear bumper sensor	1	100.00	100.00 60
19 To remove & fix rear interior garnishes & trimboard to facilitate the repairs	1	180.00	180.00 X
20 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut & weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	1,200.00	1,200.00 400
21 To putty & spray on affected areas	1	1,000.00	1,000.00 440
22 To apply rust-proofing on repaired and replaced panels	1	120.00	120.00 X
			2,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: