



Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbroy@gmail.com

Tel: 67411730

ESTIMATE

Name: Liberty Insurance Pte Ltd
Address Motor Claims Department

One Raffles Quay #25-01

North Tower

Singapore 048583

Ref Date:

04/12/2024

Ref No:

YN9973M241201

Vehicle No:

YN9973M

Model / Make:

Mitsubishi Canter

Capacity: 2998 cc

FEB21ER3SDEB (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Bumper	1213.40	1	\$ 1,929.80		Dis
2		Bumper Clips 1 set		1	\$ 50.00	SN	2u 3p/s
3		Aircon Condenser		1	\$ 2,184.50		2u 1p/s
4		Aircon Condenser Fan	820.50	1	\$ 1,439.60		2u 1p/s
5		Grille	799.20	1	\$ 1,123.40		2u 1p/s
6		Grille Clips 1 set		1	\$ 50.00	SN	2u 1p/s
7		"Canter" Emblem		1	\$ 86.00		2u 1p/s
8		"Mitsubishi Logo" Motif		1	\$ 187.00	N	2u 1p/s
9	Front Lh	Bumper Bracket		1	\$ 296.30		2u 1p/s
10		Bumper Side	408.20	1	\$ 549.00		2u 1p/s
11		Bumper Side Clips 1 set		1	\$ 45.00	SN	2u 1p/s
12		Door		1	\$ 2,129.30		2u 1p/s
13		Door Hinge Top & Lower		2	\$ 184.50		2u 1p/s
14		Door Weatherstrip		1	\$ 416.50		2u 1p/s
15		Door Lock	455.20	1	\$ 745.00		2u 1p/s
16		Door Inner Board		1	\$ 789.00		2u 1p/s
17		Door Regulator	869.20	1	\$ 1,317.70		2u 1p/s
18		Door Pillar	1110.20	1	\$ 1,672.70		2u 1p/s
19		Step Garnish Lower	366.80	1	\$ 773.20		2u 1p/s
20		Step Garnish Top		1	\$ 818.70		2u 1p/s
21		Head Lamp	945.20	1	\$ 1,712.80		2u 1p/s
22		Head Lamp Clips 01 Set		1	\$ 30.00	SN	2u 1p/s
23		Head Lamp Bulb		1	\$ 58.00	SN	2u 1p/s
24		Head Lamp Side Cover		1	\$ 584.00		2u 1p/s
25		Signal Lamp	166.00	1	\$ 324.30		2u 1p/s
26		Signal Lamp Clips 01 Set		1	\$ 20.00	SN	2u 1p/s
27		Signal Lamp Bulb		1	\$ 24.00	SN	2u 1p/s
28		Wheel Arch Fender		1	\$ 486.70		2u 1p/s
29		Spring Lock		1	\$ 250.00		2u 1p/s
30		ST Ladder Panel		1	\$ 450.00		2u 1p/s
31	Rear Lh	Cargo Box Sliding Door Panel		1	\$ 800.00		2u 1p/s
32		Side Guard		1	\$ 650.00		2u 1p/s
33	Paint door	"Corporate" Advertisement & Artwork			\$ 1,000.00	SN	2u 1p/s
34		To check all wiring & electrical component for proper function			\$ 180.00		2u 1p/s
35		To remove & refix air con, re-fill air con gas & test for leakages			\$ 350.00		2u 1p/s
36		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,200.00		2u 1p/s
37		To putty & spray painting & including touch up paint on accident affected areas			\$ 1,000.00		2u 1p/s
38		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 100.00		2u 1p/s

Total Parts & Labour of estimate for damaged vehicle

\$ 26,191.50

Total amount in Lumpsum Basis for repaired vehicle

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SDL

not Authorized
m
m
5/1/24

2/5 \$ 9600

at the time of repair

7 days



Liu's Bro Auto Engrg Wks

P 129/2-4

252

9684.30

560

1880

2724.3

9698