



Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbros@gmail.com

Tel: 67411730

ESTIMATE

Name: Liberty Insurance Pte Ltd
Address Motor Claims Department
One Raffles Quay #25-01
North Tower

Singapore 048583

Ref Date: 04/12/2024
Ref No: YN9973M241201
Vehicle No: YN9973M
Model / Make: Mitsubishi Canter
Capacity: 2998 cc FEB21ER3SDEB (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Bumper	1213.40	1	\$ 1,929.80		Dis
2		Bumper Clips 1 set	\$ 50.00	1	\$ 50.00	SN	22 3051
3		Aircon Condenser	\$ 2,184.50	1	\$ 2,184.50		But Put
4		Aircon Condenser Fan	820.50	1	\$ 1,439.60		CR
5		Grille	799.20	1	\$ 1,123.40		CR
6		Grille Clips 1 set	\$ 50.00	1	\$ 50.00	SN	17 X
7		"Canter" Emblem	\$ 86.00	1	\$ 86.00		17 X
8		"Mitsubishi Logo" Motif	\$ 187.00	1	\$ 187.00	N	17 X
9	Front Lh	Bumper Bracket	\$ 296.30	1	\$ 296.30		Dis
10		Bumper Side	408.20	1	\$ 549.00		Dis
11		Bumper Side Clips 1 set	\$ 45.00	1	\$ 45.00	SN	17 X
12		Door	\$ 2,129.30	1	\$ 2,129.30		But
13		Door Hinge Top & Lower	500	2	\$ 369.00		But
14		Door Weatherstrip	\$ 416.50	1	\$ 416.50		17 X
15		Door Lock	455.20	1	\$ 745.00		But/CR
16		Door Inner Board	\$ 789.00	1	\$ 789.00		But/CR
17		Door Regulator	869.20	1	\$ 1,317.70		But
18		Door Pillar	1110.20	1	\$ 1,672.70		But
19		Step Garnish Lower	366.60	1	\$ 773.20		CR
20		Step Garnish Top		1	\$ 818.70		NS X
21		Head Lamp	945.20	1	\$ 1,712.80		CR
22		Head Lamp Clips 01 Set	\$ 30.00	1	\$ 30.00	SN	17 X
23		Head Lamp Bulb	\$ 58.00	1	\$ 58.00	SN	17 X
24		Head Lamp Side Cover	\$ 584.00	1	\$ 584.00		NS X
25		Signal Lamp	166.00	1	\$ 324.30		But
26		Signal Lamp Clips 01 Set	\$ 20.00	1	\$ 20.00	SN	17 X
27		Signal Lamp Bulb	\$ 24.00	1	\$ 24.00	SN	17 X
28		Wheel Arch Fender	\$ 486.70	1	\$ 486.70		ground
29		Spring Lock	\$ 250.00	1	\$ 250.00		But X
30		ST Ladder Panel	\$ 450.00	1	\$ 450.00		But X
31	Rear Lh	Cargo Box Sliding Door Panel	\$ 800.00	1	\$ 800.00		But/CR
32		Side Guard	\$ 650.00	1	\$ 650.00		Dis (ep 38051N)
33	Rear door	"Corporate" Advertisement & Artwork	652		\$ 1,000.00	SN	17C 150 51N
34		To check all wiring & electrical component for proper function			\$ 180.00		20
35		To remove & refix air con, re-fill air con gas & test for leakages			\$ 350.00		100
36		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,200.00		800
37		To putty & spray painting & including touch up paint on accident affected areas			\$ 1,000.00		900
38		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 100.00		60

Total Parts & Labour of estimate for damaged vehicle

\$ 26,191.50

Total amount in Lumpsum Basis for repaired vehicle

SDL

Not Authorized
in
means
5/1/24

2/5 \$ 9600 8800
Whisper Althay
7 days

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

P 12912-4
252
9694-30
560
1880
2124-3
9692