# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 09 Dec 2024

## **Preliminary Advice**

 Vehicle No
 : PC6372G
 Accident Date
 : 29/11/2024

 Make
 : VOLVO B7R
 Policy No.
 : D24MFL008848

Assignment Date : 09/12/2024 Excess : \$\$0.00 Date of Inspection : 06/12/2024 Est. Duration of Repair : 8

Inspection At : CONNECT3 (WOODLANDS) (HQ)

566 WOODLANDS ROAD

SINGAPORE 728697

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,896.00
Revised Amount	:S\$	10,143.00
Check Items (Estimated)	:S\$	15,203.00
Total	:S\$	25,346.00
Lump Cum Donoir	.00	

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 55,000.00

 COE / PARF Rebate
 :S\$ 17,072.00

Salvage Value :S\$

Margin for Repair :S\$ 37,928.00

### Remarks

( x )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( x ) Other comments :The vehicle repair on lump sum basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.