LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sherini Pillai Date: 07 Jan 2025

Preliminary Advice

 Vehicle No
 : PC6372G
 Accident Date
 : 29/11/2024

 Make
 : VOLVO B7R
 Policy No.
 : D24MFL008848

 Assignment Date
 : 05/12/2024
 Excess
 : \$\$1,500.00

Date of Inspection : 06/12/2024 Est. Duration of Repair : 8

Inspection At : CONNECT3 (WOODLANDS) (HQ)

566 WOODLANDS ROAD (MANDAI ESTATE)

SINGAPORE 728697

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,416.00 (Orginal Est \$26,896.00 + Supp \$13
-----------------------------	------	--

Revised Amount :S\$ 24,463.00 Check Items (Estimated) :S\$ 14,218.00

Total :S\$ 38,681.00 (Inclusive of Supp \$13,520.00)

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 55,000.00

 COE / PARF Rebate
 :S\$ 17,072.00

Salvage Value :S\$

Margin for Repair :S\$ 37,928.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage
	Kindly let us have your authorisation.

-) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ($\,$ X $\,$) Other comments : The vehicle repair on Lump Sum basis.

Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost check.