



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YP 523C

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOX SLIDING DOOR LH (SN)	TO REPAIR SEE LABOUR	\$1,500.00	\$0.00
1	REAR BOX SIDE PANEL LH (SN)	TO REPAIR SEE LABOUR	\$1,200.00	\$0.00
1	REAR DOOR HOOK LH (SN)	NOT NECESSARY	\$45.00	\$0.00
1	REAR BOX "COMPANY & TEL" STICKER LH (SN)	NECESSARY	\$600.00	\$500.00
1	REAR DOOR FRAME LH (SN)	NOT NECESSARY	\$350.00	\$0.00
1	REAR BOX SIDE FRAME LH (SN) (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
			\$3,695.00	\$500.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOX SLIDING DOOR LH, REAR BOX SIDE PANEL LH AND REAR BOX SIDE FRAME LH		\$912.00	\$400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL		\$900.00	\$600.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS		\$80.00	\$20.00
			\$1,892.00	\$1,020.00
GRAND TOTAL			\$5,587.00	\$1,520.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,200.00
Report Ref No: CS1/SCD24070005/Eqh3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repossibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.