

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Quotation

DATE: 5/12/2024
VEHICLE NO: PH2822A
DRIVER: LEE KIM SENG
TYPE OF CLAIM: CLAIM 3RD PARTY
PREPARED BY: Kamarul

LOCATION: Gul Workshop
Q REF NO:
DEPARTMENT: BUS DEPARTMENT
ACCIDENT DATE: 5/12/2024
REF No: JW/1224/69

S/N	Description	Qty	Cost per Unit	Total cost W/O Gst
SPARE PARTS				
1	REAR WINDSHIELD GLASS	1	1030	1030
2	LIVERY STICKER	1	780	780
3	SIKAFLEX	5	25	125
LABOUR				
1	REMOVE AND REFIT NEW WINDSCREEN GLASS WITH SIKAFLEX	1	600	600
2	INSTALL NEW LIVERY STICKER ON REAR WINDSCREEN GLASS	1	250	250
				2785.00

1030
10% - 927

1030 ✓
780 ✓ 400
125 ✓

400

150
250 ✓

Total cost subjected to GST
Remarks: LOU 03 DAYS

Signature of Workshop

Signature of Department

Signature of Claim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting¹
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/62563561

wp' 6/12/24 @ 730pm

Resurvey new parts

taufik @ lkkauto.com

3 days

927

400

125

400

150

\$2002

03 days

#