ASS. REG. BY: Taypin - NEF: CS/SMR 24	120078 1743			
	GNMENT			
From: Dale:	Veh No: PH 28229 Yr Regn: 2017, 03			
OD TO INSTITUTE TO THE TENT TO	Type: M.Car / M.Cycle / Dog / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or			
To Inspect Vehicle No:	Make: Yntong ZK6116 ac \$494			
al Workshop m/s	Colour AC: Insured / Std / NI / NA			
of	Sp.Reading 37 2423 T/Radio; Insured / Std / NI / NA			
pened:	Eng/No:			
Policy No.	CANO: 0- LZYTBIELI.91055152			
Claims No. Sum Insured: Expass'	Gen. Cond. Good / Fair / Poor / Burnt			
Sum Insured: Excess: (Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or			
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or Modl: (NIN S/Rim / STD A/Rim or			
	Tyre Size: F: \\K22.5			
(Policy Condition)	R: 22(D)			
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /			
Bal or Market Value:	TOYO / YOKO or Ceq+			
IDAC Accident Roort Consistent? : Yes or No	R/Bal. R/Bal. R/Bal.			
GIA / PR Seer: Consistent?: Yes or No	L/Bal, 0 mm			
Est Repairs: 3 days Res.: Yes or No	D.O.A. D.O.I. 6 12 12 4			
Lum Sum: % 3 Val.: Yes or No	Survey held at Ward ands Transport			
CA REV REP. 24 HRS - VV	Des. of Damages : Frt Rear O/S N/S U/G Rooftop- or			
Date:Person Contacted: Vehicle: IN / OUT	The U/C / Chaesis frame / Roch: Strains			
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.			
Taufikh confirmed COR \$2002, 3 da	ays.			
(red, \$783, 28%)				
Onto The City Court of the Cit				
	Days Of Repair: 3			
Dala/Time, File Reburn to?	Resurvey No. of Trip: Survey Fee:			
Add Fee	: Site Insp (\$)			
	Interview (\$			
Roper Formed: Lump Sum / I.B.I: (7)	Tech. Invs (\$) where			
)	: Weel: sind (\$			

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163 Company Registration Number: 200505706E

Quotation

DATE:

DRIVER:

5/12/2024

VEHICLE NO:

TYPE OF CLAIM

PREPARED BY:

PH2822A

LEE KIM SENG

CLAIM 3RD PARTY Kamarul

LOCATION: Q REF No:

Gul Workshop

DEPARTMENT:

BUS DEPARTMENT

ACCIDENT DATE: 5/12/2024 REF No: JW/1224/69

S/N	Description	Qty	Cost per Unit	Total cost W/O Gst	en en l
	SPARE PARTS				
1	REAR WINDSHIELD GLASS	1	1030	1030	coar
2	LIVERY STICKER	1	780	780	rei
3	SIKAFLEX	5	25	125	rei-
	LABOUR				
1	REMOVE AND REFIT NEW WINDSCREEN GLASS WITH SIKAFLEX	1	600	600	400
2	INSTALL NEW LIVERY STICKER ON REAR WINDSCREEN GLASS	1	250	250	now
				2785.00	

Total cost subjected to GST

Remarks: LOU 03 DAYS

Signature of Workshop

Signature of Department

Signature of Claim

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting 1
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signatu:e:

Date:

Janfihl 97495749/62563561 WP 6/12/24@730pm

pessing new parts taufikh c/khanto.am.