



Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/112024/C0352
Date : 04-12-2024
Accident Date : 04-12-2024

Vehicle Details

Make & Model : Mercedes Benz E200K
Chassis No : WDB2110412B296599
Registration No : SKW8717L

NOT Withhold
L1 Pump & 5600/-
Painting After Rainy

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

4 days

Ex @ 250/-

1st month (6/12/24)
96910663

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER WITH NOZZLE COVER	1.00	CM \$1,150.00
2	FRONT BUMPER RETAINER LH	1.00	Dir \$90.00
3	FRONT BUMPER INNER BRACKET LH	1.00	CM \$100.00
4	FRONT BUMPER FOGLAMP LH	1.00	mt/cm \$240.00
5	FRONT BUMPER FOGLAMP COVER LH	1.00	mt \$30.00
6	FRONT BUMPER FOGLAMP CHROME GARNISH LH	1.00	mt \$90.00
7	FRONT BUMPER CHROME STRIP LH	1.00	CM \$100.00
8	FRONT BUMPER NOZZLE PIPE	1.00	Tn \$90.00
9	FRONT BUMPER UNDERCOVER	1.00	SL \$210.00
10	HEADLAMP LH	1.00	CM \$2,400.00
11	HEADLAMP PANEL LH	1.00	R \$120.00
12	FRONT FENDER LH	1.00	R \$680.00
13	FRONT FENDER "AVANTGARDE" LOGO LH	1.00	m \$70.00
14	FRONT FENDER INNERSHIELD LH	1.00	CM \$80.00
15	FRONT REINFORCEMENT BAR	1.00	R \$1,600.00
16	FRONT REINFORCEMENT BAR SPONGE	1.00	CM \$180.00

\$7,230.00

Margin: 10%

\$723.00

\$7,953.00

17 TO REPAIR DAMAGES

1.00

\$680.00

18 TO SPRAY PAINTING

1.00

\$780.00

Subtotal w/o GST:

\$9,413.00

Issued by Melvin

This is a computer-generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: