

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24120082/Uqh3m4(N)	
	16 RAFFLES QUA #42-01 HONG LEC 048581	Y NG BUILDINGSINGAPORE	Date:	31/01/2025	
	ATTN: CHRIS LIM		Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 2922R	Veh. Inspected	SMQ 9857S	
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
	Claim No.	D24010632MFCT	Excess (\$)	0.00	
	Assign From	TEO SWEE KEONG	Assign Date	05/12/2024	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ A180	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WDD1760422J658415	Colour	GREY	
	Odometer	131659 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45R17	PIRELLI	6 mm	
	L/H Front Tyre	225/45R17	PIRELLI	6 mm	
	R/H Rear Tyre	225/45R17	PIRELLI	6 mm	
	L/H Rear Tyre	225/45R17	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/12/2024	Inspection Date	23/12/2024	
	Survey held at	BLK 3022A UBI ROAD 1 #01-45/	46, SINGAPORE 408716		
	Repairer	PROGRESSIVE CAR CARE PTE LTD			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			