

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishen Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLW6319D
 TP/MSFC

M/S: MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

WS Ref: TP/MSFC

Claim Type: Third Party

Accident Date: 30/11/2024

TP Veh Reg No: SHA7807T

FAX: 65073849

Not Authorized

11 Pk @ 4350h

Repair After Rain

Estimate No: ES2401041/YISHUN

Date: 20 Dec 2024

Policy No: DMPCSNW00018402401

Veh Reg No: SLW6319D

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: JTDGG20W00J009348

Engine No: 2ZR0A74653

Reg. Date: 26/02/2018

Estimate Repair Cost to Vehicle No :SLW6319D

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	811.60	1 PC	811.60	✓
2 REAR BUMPER LH BRACKET	149.10	1 PC	149.10	✓
3 REAR BUMPER CLIP	4.00	6 PC	24.00	✓
4 REAR TAILGATE	1,998.80	1 PC	1,998.80	✓
5 TAILGATE LOGO	81.10	1 PC	81.10	✓
6 TAILGATE EMBLEM 'MATIC'	66.90	1 PC	66.90	✓
7 REAR WINDSCREEN GLASS MOULDING	230.60	1 PC	230.60	✓
8 REAR END PANEL OUTER	817.70	1 PC	817.70	✓
			4,179.80	
		Less 25%	1,044.95	3,134.85
Special Net				
9 REAR BUMPER SIDE MOULDING	60.00	1 SET	60.00	✓
10 REVERSE SENSOR	200.00	1 SET	200.00	✓
11 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
12 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
13 CAR COATING	180.00	1 PC	180.00	✓
			515.00	515.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
15 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE; TO RENEW REAR PANEL & REALIGN THE SAME	700.00	1 LA	700.00	600
16 PUTTY & RESPRAY ON TAILGATE, REAR BUMPER, REAR END PANEL	700.00	1 LA	700.00	600
17 REMOVE & REFIX FRT BUMPER, REPAIR FRT BUMPER, BONNET & REALIGN THE SAME	200.00	1 LA	200.00	180
18 PUTTY & RESPRAY ON FRT BUMPER & BONNET	450.00	1 LA	450.00	400
19 RUSTPROOFING	30.00	1 LA	30.00	✓
			2,180.00	2,180.00
		Total		SS 5,829.85
		Add GST @ 9%		524.69
		Total Amount Payable		SS 6,354.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

4030.70
 Supp 129.00

\$ 4159.70
 Less 25% 1039.92

\$ 3119.78

SN 515.00

Lab 1910.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLW6319D
SUPP

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/MSFC

Claim Type: Third Party

Accident Date: 30/11/2024

TP Veh Reg No: SHA7807T

Estimate No: ES2401041/YISHUN

Date: 24 Dec 2024

Policy No: DMPCSNW00018402401

Veh Reg No: SLW6319D

Make/Model: TOYOTA TOYOTA
WISH 1.8 CVT

Chassis No: JTDGG20W00J009348

Engine No: 2ZR0A74653

Reg. Date: 26/02/2018

Estimate Repair Cost to Vehicle No :SLW6319D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR SMART KEY SENSOR	129.00	1 PC	CM 129.00 ✓	
			129.00	
		Less 25%	32.25	96.75
Total				S\$ 96.75
GST Amount				S\$ 8.71
Total Amount Payable				<u>S\$ 105.46</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE