9/3/24, 11:57 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070006/RPA3Q2

Date: 03/09/2024

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0007246

**Claimant Vehicle** SNQ3780G Insured Vehicle No: SNC492G

No:

Date of Loss: 27/06/2024 Nature of Claim: TP Claim No: MPC2024D0008112

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SNQ3780G** 

Make & Model: HYUNDAI SX2 KONA, 1.6 GDI HEV (A) Engine No: G4LLRU413673 Reg. Date: 15/04/2024 (Man. Year: 2024) KMHHB811VRU058690 Chassis No:

Colour: Red Odometer: 4381 km

**Engine Capacity:** 1580 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Engine Modification: No Handbrake (Serviceable): Yes

**CONDITION OF TYRES** 

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16 Front Left Side: Rear Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,514.50	635.00	879.50	58.07
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,380.00	1,390.00	1,990.00	58.88
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	4,894.50	2,025.00	2,869.50	58.63

0.00 Global Sum Settlement (S\$)

**INSPECTION** 

Date of Assignment: 01/07/2024

Komoco Motors Pte Ltd (HQ) Date Inspected: 25/07/2024 Inspected At: 253 ALEXANDRA ROAD, #01-01

Singapore 159936

Estimated Period of Repair: 3.0 days

**CHEW HSIAO TONG** Adjuster: MOHD RASUL Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/3/24, 11:57 AM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Sep 2024)

Parts: 192 HYUNDAI SX2 KONA 1.6 GDI HEV (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNQ3780G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY-FR BUMPER LWR	*Check	1,100.00 FL	*- FL
2	1		*COVER ASSY-FR BUMPER UPR	Scratched	726.00 FL	*726.00 FL
3	1		*MOULDING -FRONT BUMPER RH	Scratched	74.00 FL	*74.00 FL
4	1		*BRACKET ASSY -FR BUMPER SIDE ,LH	*Check	20.00 FL	*- FL
5	1		*BRACKET ASSY -FR BUMPER SIDE RH	*Check	20.00 FL	*- FL
6	10		*REAR BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
7	6		*UPPER GRILLE CLIP	Not Necessary	6.00 FL	*- FL
8	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,006.00	840.00
	- List Item Discount on L Items 25.00/25.00% (S\$)			491.50	205.00	
				Total Parts (S\$)	1,514.50	635.00

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			,
1	TO CARRY OUT ACCIDENT BODY REPAIR -FRT BUMPER UPR /FRT BUMPER LWR	New	1,840.00	460.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT BUMPER UPR/FRT BUMPER LWR	New	1,140.00	570.00
3	TO REALIGN BOTH FRT HEADLAMP	New	40.00	0.00
4	TO CHECK FOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER	New	180.00	180.00
5	TO REPROGRAMME AFTER ACCIDENT REPAIR	New	180.00	180.00
	Gross Labou	r Cost (S\$)	3,380.00	1,390.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >