

Date :

III Insurance Pte Ltd
Attn: Motor Claims Department

Vehicle number : **SNQ3780G**
Make and model : KONA 1.6 DCT GL HYBRID
Registration Date : 15/04/2024
Chassis number : KMHBB811VRU058690
Engine number : G4LLRU413673

Claim Officer : Robyn
Job No. :
Owner name : ALWYN PEH BOON
Date of Acc : 27/6/2024
Policy number CN51028893
Claim Type : **TP CLAIM**

Items :			2nd	Estimate	Revised
1	COVER ASSY-FR BUMPER LWR	86560BE010		\$ 1,100.00	
2	COVER ASSY-FR BUMPER UPR	86510BE100		\$ 726.00	
3	MOULDING-FRONT BUMPER,RH	86596BE000		\$ 74.00	
4	BRACKET ASSY-FR BUMPER SIDE,LH	86551BE000		\$ 20.00	
5	BRACKET ASSY-FR BUMPER SIDE,RH	86552BE000		\$ 20.00	
6	REAR BUMPER CLIP X10	865952T500		\$ 20.00	
7	UPPER GRILLE CLIP X6	1420608250B		\$ 6.00	
				\$ 1,966.00	
Less 25% Discount				\$ 491.50	
Material total				\$ 1,474.50	

Vehicle number

Body,Paint & Labour Items :		Estimate	
1	To carry out accident body repair - FRT BUMPER UPR / FRT BUMPER LWR	\$	1,840.00
2	Complete putty and spray paint all affected areas - FRT BUMPER UPR / FRT BUMPER LWR	\$	1,140.00
Labour Charges:	2nd	Estimate	Revised
3	TO REALIGN BOTH FRT HEADLAMP (S.NETT)	\$	40.00
7	TO CHECK FOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ,	\$	180.00
8	TO REPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00
9	SUNDRIES (S.NETT)	\$	40.00
Total Labour		\$	3,420.00
Total Parts		\$	1,474.50
Excess		\$	-
		\$	4,894.50
Add GST 9%		\$	440.51
Grand Total		\$	5,335.01

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***