

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Hui Rong

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation
 DATE : 25.02.2025
 VEH NO : SNH732M
 MODEL : Honda Vezel
 D O A : 04.12.2024
 YR REF : SKV7063B

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SNH732M (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Debond</i>	1	907.20 ✓
2	Rear Bumper Lower Garnish <i>lit</i>	1	638.20 ✓
3	Rear Bumper Diffuser <i>ton</i>	1	304.90 ✓
4	Rear Bumper Reflector	2	161.00 +
5	Rear Bumper Side Bracket <i>3 new rec</i>	2	310.00 +
6	Rear Bumper Side Retainer	2	53.60 +
7	Reverse Sensor <i>1 piece dmd</i>	2	604.80 302.40
8	Reverse Sensor Holder <i>1 piece new</i>	4	156.80 25.
9	Reverse Sensor Wire Harness <i>new rec</i>	1	463.20 +
10	Rear Camera <i>new rec</i>	1	763.20 +
11	Tailgate <i>Repair</i>	1	1,288.40 +
12	Tailgate Outer Garnish <i>Debond</i>	1	801.20 —
13	Tailgate Logo <i>new</i>	1	58.90 —
14	Tailgate Emblem "VEZEL" <i>new</i>	1	43.70 —
15	Tailgate Top Lock <i>new</i>	1	380.10 +
16	Tailgate Lower Lock <i>new</i>	1	39.20 +
17	Tailgate Inner Trim Board <i>new</i>	1	335.90 +
18	Tailgate Weatherstripe <i>new</i>	1	211.90 +
19	Tailgate Windscreen Moulding <i>new</i>	1 set	149.70 +
20	Rear End Panel <i>Repair</i>	1	595.60 +
21	Rear End Panel Top Garnish <i>new</i>	1	186.90 +
22	Rear En Panel Buzzer <i>new</i>	1	85.90 +
23	Rear End Panel Antenna Sensor <i>new</i>	1	185.90 +
			3081.50
			2465.20
			\$ 8,726.20
Less 20%			\$ (1,745.24)
			\$ 6,980.96

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SNH732M (HONDA VEZEL)

1	Rear Number Plate	at	1	30.00	✓
2	Rear Number Plate Holder	new	1	30.00	+
3	Rear Bumper Clips	new	1 set	30.00	✓
4	Rear End Panel Sealant	new	1	60.00	+
5	Rear End Panel Top Garnish Clips	new	1 set	20.00	+
6	Tailgate Inner Trim Board Clips	new	1 set	30.00	+
7	Tailgate Outer Garnish Clips	new	1 set	20.00	✓
8	Rear Camera	new	1	480.00	+

700.00

Total parts

\$ 7,680.96

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$	1,200.00	400
2	To putty & spray up paint works	\$	1,200.00	500
3	To check wiring	\$	50.00	30
4	To apply tuff coat	\$	150.00	40
5	To remove & refix reverse sensor & distance setting	\$	100.00	50
6	To remove & refix rear video recorder	\$	100.00	X
7	To remove and refix rear camera & perform distance setting	\$	100.00	X
8	To transfer tailgate fittings	\$	150.00	X
9	To remove & refix tailgate glass	\$	180.00	X

Total Labour

\$ 3,230.00

Grand Total

\$ 10,910.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

GST Will be reflected in the final bills

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NOTE : -

Acknowledged by Repairer

Signature:

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE

FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 3565.20.
H/S: 2850