



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/122024/C0350
Date : 02-12-2024
Accident Date : 01-12-2024

Vehicle Details

Make & Model : Suzuki JIMNY SIERRA 1.5JC *Kenner*
AUTO
Chassis No : JB74W107956 *HP: 98910663*
Registration No : SML8476R

Not Authorized
LI Pay @ 4000/-
Repairing After Repair
Ex TRA

S/N	Description	Qty	Amount (\$S)	
1	FRONT BONNET (O)	1.00	<i>Bz</i> \$850.00	<i>✓</i>
2	FRONT GRILLE (O)	1.00	<i>CM</i> \$450.00	<i>✓</i>
3	FRONT GRILLE CHROME LOGO	1.00	<i>in</i> \$30.00	<i>✓</i>
4	FRONT GRILLE PANEL (TOP & BOTTOM) (O)	1.00	<i>Bz</i> \$580.00	<i>✓</i>
5	FRONT FENDER LH (O)	1.00	<i>Bz</i> \$160.00	<i>✓</i>
6	FRONT FENDER GARNISH LH	1.00	<i>Bz</i> \$180.00	<i>✓</i>
7	HEADLAMP LH (O)	1.00	<i>mf CM</i> \$1,200.00	<i>2</i>
8	HEADLAMP PANEL LH (TOP)	1.00	<i>Bz</i> \$50.00	<i>2</i>
9	FOGLAMP LH (O)	1.00	<i>in</i> \$320.00	<i>1</i>
10	FOGLAMP WIRING HARNESS (O)	1.00	<i>Tn</i> \$50.00	<i>2</i>
			\$3,870.00	
Margin: 10%			\$387.00	
			\$4,257.00	
11	TO REPAIR DAMAGE	1.00	\$680.00	<i>500/-</i>
12	TO SPRAY PAINTING	1.00	\$780.00	<i>600/-</i>
Subtotal w/o GST:			\$5,717.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Melvin

This is a computer-generated document. No signature is required.