

7 day,

Q 12,392.31



ESTIMATE TO REPAIR

VEHICLE NO. : SNR 6832 R
MAKE : HYUNDAI
MODEL : SX2 KONA 1.6 GDI HEV
YEAR : 2024
CHASSIS NO : KMHHB811VRU071103

SURVEYOR NAME :

DATE OF SURVEY :

TIME OF SURVEY :

DATE : 06-Dec-24

DATE OF ACCIDENT : 28-Nov-24

THIRD PARTY REF : SFB 1819 S / ECICS

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper 1015			Net form	\$ 1,015.00
1 pc	rear bumper lower diffuser 510	39		ms cm	\$ 856.70
1 pc	rear bumper rh lamp			\$ Sn	953.00
1 pc	rear bumper rh retainer			\$ cm	32.00
1 pc	rear bumper rh cover			\$ cm	201.00
1 pc	rear rh fender undershield			\$ D11	275.00
1 pc	rear rh fender arch garnish			\$ Sn	473.00
1 pc	rear rh radar			\$ Sn	1,568.00
1 pc	rear rh door 2063			R1	\$ 2,063.00
1 pc	rear rh door frame tape			\$ na	55.00
1 pc	rear rh door protector			\$ wt	485.00
1 pc	rear rh door regulator			\$ Sn	277.00
1 pc	rear rh door power window Motor			\$ Sn	370.00
1 pc	rear rh door channel			\$ Sn	241.00
1 pc	rear rh door rubber			\$ Sn	171.00
1 pc	rear rh door check			\$ Sn	50.00
2 ps	rear rh door hinges		\$ 120.00	\$ R1	240.00
1 pc	front rh door 1789			\$ R1	1,789.00
1 pc	front rh door protector			nd 1 wt	485.00
1 pc	front rh door lock			\$ R	398.00
1 pc	front rh door frame tape			\$ na	85.00
1 pc	front rh rubber			\$ Sn	153.00
1 pc	front rh door regulator			\$ Sn	283.00
1 pc	front rh door power window motor			\$ Sn	370.00
1 pc	front rh door channel			\$ Sn	241.00
1 pc	rh side skirt			\$ Sn	600.00
1 pc	front rh fender arch garnish			\$ wt	473.00
1 pc	front rh fender under-shield			\$ Sn	163.00
1 pc	front bumper			n Sn ms cm	\$ 726.00
1 pc	front bumper lower 1100	2216		\$ wt	1,100.00
1 pc	front bumper rh lamp			\$ wt	2,216.00
1 pc	front bumper rh retainer			\$ D11	25.00
2 ps	rim		\$ 883.00	\$ nd	1,766.00
1 pc	front rh knuckle arm			\$ Sn	518.00
1 pc	front rh lower arm			\$ Sn	808.00
1 pc	front rh lower arm ??			\$ Sn	107.00
1 pc	front rh shock absorber			\$ Sn	490.00
	Balance C/F				\$ 22,121.70

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd



	Balance B/F				\$ 22,121.70	
1 pc	front stabilizer bar				\$ Sm 383.00	X
1 pc	front steering link				\$ Sm 143.00	X
1 pc	front wheel bearing hub				\$ Sm 721.00	X
					\$ 23,368.70	
	Less 20%				\$ 4,673.74	
					\$ 18,694.96	
	To putty and spray paint.				\$ 1,800.00	1000
	towing				\$ 100.00	600
	to transfer door fitting				\$ 100.00	✓
	to replace front under carriage			nn	\$ 350.00	X
	to check wheel alignment				\$ 800.00	1200
	to anti rust				\$ 150.00	600
	labour charges				\$ 1,600.00	8000
TG-BN/-	Total				\$ 23,594.96	

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd