

MSIG

VEHICLE NO.: SHD 3050 U

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>Replaced</i>	1	\$ 1,015.00	\$ 1,015.00
BEAM-REAR BUMPER <i>Replaced</i>	1	\$ 582.00	\$ 582.00
STAY-RR BUMPER,(LH/RH) <i>new</i>	2	\$ 55.00	\$ 110.00
BRACKET ASSY-RR BUMPER LWR,(LH/RH) <i>new</i>	2	\$ 32.00	\$ 64.00
CAP-RR HOOK <i>new</i>	1	\$ 11.00	\$ 11.00
DIFFUSER ASSY-RR BUMPER <i>Replaced</i>	1	\$ 856.70	\$ 856.70
PARKING SENSOR <i>new</i>	2	\$ 262.00	\$ 524.00
PARKING SENSOR WIRE <i>new</i>	1	585.35	\$ 585.35
REAR END PANEL <i>Replaced</i>	1	\$ 729.00	\$ 729.00
REAR END PANEL GARNISH <i>broken</i>	1	\$ 190.00	\$ 190.00
PANEL ASSY-TAIL GATE <i>Replaced</i>	1	\$ 2,164.00	\$ 2,164.00
HINGE ASSY-TAIL GATE (LH/RH) <i>new</i>	2	\$ 28.00	\$ 56.00
TRIM ASSY-TAIL GATE LWR <i>changed</i>	1	\$ 378.00	\$ 378.00
TRIM ASSY-TAIL GATE UPR <i>new</i>	1	\$ 63.00	\$ 63.00
TRIM ASSY-TAIL GATE FRAME SIDE (LH/RH) <i>new</i>	2	\$ 39.00	\$ 78.00
W/STRIP-TAIL GATE OPNG <i>changed</i>	1	\$ 137.00	\$ 137.00
LATCH ASSY-TAIL GATE <i>1st / Done</i>	1	\$ 278.00	\$ 278.00
STRIKER ASSY-T/GATE <i>new</i>	1	\$ 25.00	\$ 25.00
HANDLE ASSY-TAIL GATE O/S <i>new</i>	1	\$ 125.00	\$ 125.00
LIFTER ASSY-TAIL GATE,(LH/RH) <i>new</i>	2	\$ 111.00	\$ 222.00
BOOT TOP COVER CTR <i>new</i>	1	\$ 455.00	\$ 455.00
BOOT EMBLEM-SYMBOL MARK <i>1st</i>	1	\$ 72.00	\$ 72.00
EMBLEM-KONA <i>1st</i>	1	\$ 97.00	\$ 97.00
EMBLEM-HYBRID <i>new</i>	1	\$ 47.00	\$ 47.00
SPOILER-RR <i>new</i>	1	\$ 1,347.00	\$ 1,347.00
GARNISH ASSY-TAIL GATE <i>new</i>	1	\$ 375.00	\$ 375.00
REAR NUMBER PLATE LAMP <i>broken</i>	2	\$ 231.00	\$ 462.00
3RD BRAKE LAMP ASSY-CENTER POSITION <i>broken</i>	1	\$ 6,604.00	\$ 6,604.00
LAMP ASSY-REAR COMB OUTSIDE,LH <i>new</i>	2	\$ 717.00	\$ 1,434.00
LAMP ASSY-REAR COMB LH,LWR <i>new</i>	2	\$ 953.00	\$ 1,906.00
LAMP ASSY-REAR FOG <i>new</i>	1	\$ 163.00	\$ 163.00
3RD BRAKE LAMP ASSY-HMS <i>new</i>	1	\$ 220.00	\$ 220.00
UNIT ASSY-REAR VIEW CAMERA <i>new</i>	1	\$ 1,088.00	\$ 1,088.00
REAR MUFFLER <i>new</i>	1	\$ 1,341.00	\$ 1,341.00
REAR MUFFLER HEAT SHIELD <i>new</i>	1	\$ 235.00	\$ 235.00
REAR MUFFLER MOUNTING <i>new</i>	2	\$ 22.00	\$ 44.00
SUB TOTAL			\$ 24,083.05

1306.00

$$\begin{array}{r} 8.47670 \\ 6.78136 \\ \hline \end{array}$$

LESS 20%				\$ 4,816.61
DISCOUNTED TOTAL				\$ 19,266.44
REAR NUMNER PLATE <i>broken</i>	SN	1	\$ 45.00	\$ 45.00
COMFORT LOGO <i>Hee</i>	SN	1	\$ 80.00	\$ 80.00
REAR WINDSCREEN SEALANT <i>Hee</i>	SN	1	\$ 46.00	\$ 46.00
SUB TOTAL				\$ 171.00
Labour Charge				
Panel Beating	1	\$2,000.00	\$ 2,000.00	
Spray Painting Charge	1	\$1,600.00	\$ 1,600.00	
Wiring Charge	1	\$100.00	\$ 100.00	
Tuff Kote	1	\$100.00	\$ 100.00	
Towing Charge	1	\$80.00	\$ 80.00	
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$ 150.00	
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$ 120.00	
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$ 550.00	
TOTAL LABOUR				\$ 4,700.00
ESTIMATE TOTAL				\$ 24,137.44
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

✓
✓
✓

171.00

600/-
400/-
30/-
20/-
80/-
80/-
44

1210.00

09/12/2024 @ 1300m

P/P 8,162-36

N/A Actual

Part by Part

5 days

[Signature]

Photo after

LKK Auto

sign

with damage

Part.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: