

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0512/2024/KS
DATE : 1-Jul-24
WIP : 21406

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/7/2024

YOUR INSURED VEHICLE NO : SKW 6199 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS CHAN HONG CHOO
ADDRESS : 9 JALAN MATA AYER
#03-55
SINGAPORE 759153
TELEPHONE : HP +65 97835274
TYPE OF CLAIM : THIRD PARTY CLAIMS
POLICY NO : 7230064451
VEHICLE NO : SLQ 5716 D
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 14/7/2017
ENGINE NO : CVN 038995
CHASSIS NO : WAUZZZF44HA164740
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Jun-24
PLACE OF ACCIDENT : 9 JALAN MAYA AYER, SINGAPORE 759153
BASEMENT CARPARK LOT NEAR BLK 7

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLQ 5716 D.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT AND CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	/
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000 by PPA
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	1,800.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	/
TOTAL LABOUR CHARGES		:	<u>\$ 4,902.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / DEF	1	\$	2,670.00	
2	FRONT BUMPER FIXINGS PARTS X	1		TBC	
3	FRONT BUMPER SECURING STRIP X	2	\$	90.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	1	\$	286.00	
5	FRONT BUMPER AIR GUIDE - RH ?	1	\$	8.00	
6	RADIATOR GRILLE - RH X	1	\$	1,371.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH X	1	\$	169.00	
8	FRONT BUMPER GUIDE SECTION - RH ?	1	\$	46.00	
9	FRONT BUMPER BRACKET - RH ?	1	\$	173.00	
10	FRONT BUMPER REINFORCEMENT BEAM X	1	\$	1,033.00	
11	FRT LOCK CARRIER TOP SUPPORT BRACKET - LH / RH X	2	\$	74.00	
12	OUTSIDE TEMP SENSOR BRACKET X	1	\$	30.00	
13	LED HEADLIGHT - RH / cut	1	\$	9,325.00	
14	LED HEADLIGHT SPACER - RH ?	3	\$	150.00	
15	LIFT CYLINDER - RH X	1	\$	252.00	
16	LIFT CYLINDER BRACKET - RH X	1	\$	8.00	
17	LIFT CYLINDER HOSE X	1	\$	118.00	
18	FRONT FENDER - RH / 00	1	\$	918.00	
19	FRONT FENDER ATTACHMENT PARTS - RH X	1	\$	241.00	
20	FRONT FENDER BRACKET - RH X	1	\$	45.00	
SUB TOTAL SPARE PARTS		:	\$	17,007.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 5716 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - RH ✓	1	\$	72.00
22	FRONT FENDER RIVET - RH ✓ / ✓	6	\$	26.00
23	FRONT FENDER BRACKET - RH ?	1	\$	67.00
24	FRONT FENDER BRACKET - RH .	1	\$	42.00
25	FRONT FENDER BRACE - RH X	1	\$	177.00
26	FRONT WHEEL HOUSING LINER - RH X	1	\$	294.00
27	FRONT WHEEL HOUSING LINER ATTACHMENT - RH X	1		TBC
28	FRONT WHEEL SPOILER ✓	1	\$	92.00
29	FRONT FENDER COVER - RH X	1	\$	76.00
30	FRONT FENDER LEDGE COVER - RH LONG X	1	\$	39.00
31	FRONT FENDER LEDGE COVER - RH SHORT X	1	\$	29.00
32	SUNDRIES ?		\$	500.00
TOTAL SPARE PARTS		:	\$	18,421.00
TOTAL LABOUR CHARGES		:	\$	4,902.00
GRAND TOTAL		:	\$	23,323.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
5/7/24, 10.00 am
m k
4 dgr
My Policy

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT