

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SGK 9882X**

Made : **Honda**

Model : **Accord Euro-R 2.0 M**

Chassis No : **CL71201111**

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper / DD	1	\$ 1,069.20	\$ 1,069.20
2	Rear Bumper Reflector RH X nn	1	\$ 64.10	\$ 64.10
3	Rear Bumper Reflector LH X nn	1	\$ 64.10	\$ 64.10
4	Rear Bumper Side Retainer RH / BR	1	\$ 35.70	\$ 35.70
5	Rear Bumper Side Retainer LH / BR	1	\$ 35.70	\$ 35.70
6	Rear Bumper Reinforcement X nn	1	\$ 340.00	\$ 340.00
7	Rear Bootlid X R	1	\$ 750.10	\$ 750.10
8	Rear Bootlid Lock Assembly X nn	1	\$ 281.40	\$ 281.40
9	Rear Bootlid Weatherstrip / TM	1	\$ 125.00	\$ 125.00
10	Rear Bootlid Taillamp Assembly RH X nn	1	\$ 261.20	\$ 261.20
11	Rear Bootlid Taillamp Assembly LH X nn	1	\$ 261.20	\$ 261.20
12	Rear Bootlid Emblem / M	1	\$ 53.50	\$ 53.50
13	Rear Bootlid "Accord" Emblem / M	1	\$ 30.20	\$ 30.20
14	Rear Bootlid "Euro-R" Emblem / M	1	\$ 31.80	\$ 31.80
15	Rear Taillamp Assembly RH X nn	1	\$ 315.00	\$ 315.00
16	Rear Taillamp Assembly LH X nn	1	\$ 315.00	\$ 315.00
17	Rear End Panel / DD	1	\$ 620.00	\$ 620.00
18	Rear End Panel Top Garnish X nn	1	\$ 105.00	\$ 105.00
19	Rear Spare Tyre Panel Top Board X nn	1	\$ 325.30	\$ 325.30
20	Rear Spare Tyre Panel X nn	1	\$ 899.50	\$ 899.50
21	Rear Fender Inner Trim RH X nn	1	\$ 428.00	\$ 428.00
22	Rear Fender Inner Trim LH X nn	1	\$ 428.00	\$ 428.00

2157.50
-20%
1726

Parts Sub Total : \$ 6,839.00

20% Discount \$ 1,367.80

PARTS TOTAL : \$ 5,471.20

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate X nn	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set / M	1	\$ 50.00	\$ 30 / 50.00
3	Rear Bootlid Inner Trim Clips - Set X nn	1	\$ 50.00	\$ 50.00
4	Rear Taillamp Assembly Clips - Set X nn	1	\$ 50.00	\$ 50.00

5	Rear End Panel Top Garnish Clips - Set X nn	1	\$	40.00	\$	40.00
6	Rear Fender Inner Trim Clips - Set X nn	1	\$	80.00	\$	80.00
7	Rear Bootlid Sealant x nn	1	\$	150.00	\$	150.00
8	Rear End Panel Sealant X / PC	1	\$	150.00	\$	30 / 150.00
9	Rear Floor Panel Sealant y nn	1	\$	150.00	\$	150.00
10	Rear Fender RH Sealant y nn	1	\$	150.00	\$	150.00
11	Rear Fender LH Sealant x nn	1	\$	150.00	\$	150.00
12	Rear Windscreen Glass Sealant X nn	1	\$	120.00	\$	120.00
13	Rear "HKS" Exhaust Pipe - Aftermarket X nn	1	\$	2,500.00	\$	2,500.00
14	Rear Bootlid Reverse Camera X nn	1	\$	500.00	\$	500.00
15	Rear Bumper Reverse Sensor / Shipped	1	\$	300.00	\$	300.00
SPECIAL NETT TOTAL :					\$	4,490.00

* Rear Bumper inner spoiler 450 ✓ BR 380 / 610

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 800 2,400.00
2	To Spray Paint Affected Areas	\$ 600 1,800.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Rear Windscreen Glass	\$ X 150.00
5	To Transfer Rear Bootlid Mechanism	\$ X 150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30 120.00
7	To Remove & Refix Rear Bootlid Reverse Camera	\$ X 150.00
8	To Remove & Refix Rear Exhaust Pipe	\$ X 120.00
9	To Remove & Refix Fuel Tank	\$ X 200.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 50 150.00
11	To apply anti rust on affected parts	\$ 30 200.00
12	To Conduct Water Leak Test	\$ X 100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 6,120.00

1540

Steve (LKK)
9/12/24, 1.00pm
m R
L/S
LJ AL SM
6 days

PARTS TOTAL : \$ 5,471.20
SPECIAL NETT TOTAL : \$ 4,490.00
LABOUR TOTAL : \$ 6,120.00
GRAND TOTAL : \$ 16,081.20

3876

L/S - 3100.80
= 3100

3950.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: -

Date: