

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

IS First Capital

Agropolis Pte Ltd

ation no. : GBF 7845 C / Nissan Cabstar 3.0 5M/T ABS

nt Date: 3/12/2024

9-Dec-24

Quotation no: 78451203

Qty	Item	Amount
<u>LIST ITEMS</u>		
1	Taillamp RH <i>287.20</i>	<i>CM</i> \$485.00 ✓
1	Tail gate	<i>R</i> \$1,250.80 X
1	Spare tyre bracket	<i>R</i> \$267.00 X
3	Tailgate hinge <i>0110.00</i>	<i>Di</i> \$855.00 ✓
1	Tailgate safety lock	<i>R</i> \$126.00 ✓
		\$2,983.80
<i>ipc stopper</i>	<i>- \$45/-</i>	Less 10% <i>10%</i> \$447.57
		\$2,536.23

<u>SPECIAL NETT ITEM</u>		
1	Sticker 70 km/h	<i>15in</i> \$25.00
1	Company logo art	<i>Me</i> \$480.00 <i>100%</i>
1	Sticker 6 Pax	<i>Me</i> \$25.00 <i>15in</i>
2	Reverse Sensor <i>Shan</i>	<i>2008N</i> <i>P</i> \$456.00 X
1	P Plate Decal	<i>Me</i> \$10.00 ✓
		\$996.00

LABOUR & MISC CHARGES

To knock out the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. *400l* \$700.00

To remove and replace RH taillamp and check for the wiring *20l* \$50.00

Supply spray paint material and necessary items to respray on the accident damage area and other affected area / panel. *400l* \$600.00

TOTAL \$1,350.00
Total Parts and Labour Cost of Repair **\$4,882.23**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Not Notified
11 Nov @ 1300h
Meany After Rain
2 days