

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBF 7845C

REPLACEMENT OF PARTS							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	TAILLAMP RH	CRACKED	\$485.00	\$287.20			
1	TAIL GATE	TO REPAIR SEE LABOUR	\$1,250.80	\$0.00			
1	SPARE TYRE BRACKET	TO REPAIR SEE LABOUR	\$267.00	\$0.00			
3	TAILGATE HINGE @\$282.00	DISTORTED (1PC ONLY)	\$855.00	\$110.00			
1	TAILGATE SAFETY LOCK	BENT	\$126.00	\$126.00			
1	STOPPER	MISSING	\$45.00	\$45.00			
	LESS 10.00% DISCOUNT		(\$302.88)	(\$56.82)			
		\$2,725.92	\$511.38				

Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	STICKER 70KM/H (SN)	NECESSARY	\$25.00	\$15.00			
1	COMPANY LOGO ART (SN)	NECESSARY	\$480.00	\$100.00			
1	STICKER 6 PAX (SN)	NECESSARY	\$25.00	\$15.00			
2	REVERSE SENSOR @\$228.00 (SN)	SHORTED	\$456.00	\$200.00			
1	P PLATE DECAL (SN)	NECESSARY	\$10.00	\$10.00			
			\$996.00	\$340.00			

Labour						
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
TO KNOCK OUT THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF TAIL GATE AND SPARE TYRE BRACKET		\$700.00	\$400.00			
TO REMOVE AND REPLACE RH TAILLAMP AND CHECK FOR THE WIRING		\$50.00	\$20.00			
SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON THE ACCIDENT DAMAGE AREA AND OTHER AFFECTED AREA / PANEL		\$600.00	\$400.00			
		\$1,350.00	\$820.00			
CPAND TOTAL	<b>\$5,071,92</b>	¢1 671 38				

GRAND TOTAL	\$5,071.92	\$1,671.38		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,300.00		
Report Ref No: CS/FCI24120101/Kqh3e2				

MARKET VALUE: \$24,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,454.00=NETT VALUE: \$18,546.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.