



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 ATTN: CHARMAINE KONG			Ref: CS/LPC24120102/Uvh3m4(N) Date: 04/03/2025 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XD 9400P	Veh. Inspected	PD 1240G
	Policy No.	Z24VC05000971	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030288	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	09/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA COASTER 23 SEATER	c.c	4009
	Engine No.	HIDDEN	Year of Reg.	2023
	Chassis No.	JTGBDAC8706600292	Colour	WHITE
	Odometer	102568 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/75R17.5	GT RADIAL	6 mm
	L/H Front Tyre	215/75R17.5	GT RADIAL	6 mm
	R/H Rear Tyre	215/75R17.5 (D)	GT RADIAL	6/6 mm
	L/H Rear Tyre	215/75R17.5 (D)	GT RADIAL	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/12/2024	Inspection Date	05/02/2025
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	