

CD/TIL 24120103/Dama³

ASSIGNMENT

CBE 27 June 2032

From: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / MV / MV

To inspect Vehicle No: _____

at Workshop in/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

Sta. / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 98 days Res: Yes or No

Lump Sum: 10 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STD 6805 P Yr Reg: 28 June 2024

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Pirus Co. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: H.A. T/Radio: Insured / Std / NI / NA

Eng/No: 2ZR2Y84889

C/No: JTDAB3AU303004860

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/60 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front _____ Rear _____

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 02/12/2024 D.O.I. 10/12/2024

Survey held at Kiprost Wyang

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Roofing or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TIL GBH 7394B

L/Sum 10% COS no after repair with damaged parts

18/12/24 Pump H/S 14,000/- with 9 19s 2 sy

Data Time, File Path: 17 ☐ Prefl. Report11 ☐ Final Report

Data Time, File Path: 17

2

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transporter:

S-RS \$

Photos

Other

TOTAL

Report Format: _____

Lump Sum / L.B. (\$ _____)

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 7-Dec-24

INSURANCE: III

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD 6805 P

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR TRUNK LID COVER <i>BB BNC 2280-10</i>	1	\$ 2,515.30	\$ 2,515.30	✓
REAR TRUNK LID LOCK <i>Dam</i>	1	\$ 684.90	\$ 684.90	✓
REAR TRUNK LID COVER TRIM BOARD <i>bt</i>	1	\$ 655.50	\$ 655.50	✓
Boot Lid Trimboard, top <i>HH</i>	1	\$ 268.00	\$ 268.00	X
Boot Lid Trimboard SIDE (LH/RH) <i>cut</i>	2	\$ 161.30	\$ 322.60	✓
REAR TRUNK OUTER LAMP <i>broken</i>	1	\$ 1,529.20	\$ 1,529.20	✓
Boot Lid outer lamp side cover <i>HH</i>	2	\$ 78.70	\$ 157.40	X
REAR TRUNK LID RUBBER <i>deformed</i>	1	\$ 483.40	\$ 483.40	✓
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$ 85.82	\$ 85.82	✓
REAR TRUNK LID LOGO (HE V) <i>Hec</i>	1	\$ 73.96	\$ 73.96	✓
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$ 101.00	\$ 101.00	✓
THIRD BRAKE LIGHT <i>broken</i>	1	\$ 989.70	\$ 989.70	✓
REAR TRUNK LID HINGE (LH/RH) <i>HH</i>	2	\$ 177.80	\$ 355.60	X
REAR TRUNK LID ABSORBER <i>HH</i>	2	\$ 478.30	\$ 956.60	X
REAR WINDSCREEN GLASS <i>shattered 1823.20</i>	1	\$ 2,306.50	\$ 2,306.50	✓
REAR WINDSCREEN MOULDING <i>Hec</i>	1	\$ 81.50	\$ 81.50	✓
REAR NUMBER PLATE LAMP <i>broken</i>	2	\$ 94.70	\$ 189.40	✓
REAR BUMPER <i>Dam 595.10</i>	1	\$ 855.60	\$ 855.60	✓
REAR BUMPER RE-INFORCEMENT <i>broken 451.50</i>	1	\$ 549.99	\$ 549.99	✓
REAR BUMPER LOWER GARNISH <i>broken 511.10</i>	1	\$ 741.70	\$ 741.70	✓
REAR BUMPER LOWER COVER <i>deformed</i>	1	\$ 391.20	\$ 391.20	✓
REAR BUMPER SIDE RETAINER <i>SH</i>	2	\$ 192.10	\$ 384.20	X
REAR BUMPER TOWING COVER <i>broken</i>	1	\$ 19.70	\$ 19.70	✓
REAR BUMPER CLIPS <i>Hec</i>	1	\$ 40.00	\$ 40.00	✓
REAR BUMPER BRACKET <i>HH</i>	2	\$ 113.20	\$ 226.40	X
REAR BUMPER UNDER SIDE COVER <i>HH</i>	2	\$ 327.47	\$ 654.94	X
REAR BUMPER SIDE GARNISH <i>HH</i>	2	\$ 116.73	\$ 233.46	X
REAR BUMPER SIDE REFLECTOR <i>mostly broken / cut</i>	2	\$ 298.90	\$ 597.80	✓
REAR BUMPER SENSOR WIRE <i>HH</i>	1	\$ 424.60	\$ 424.60	X

REAR BUMPER REVERSE SENSOR	src	4	\$ 494.20	\$ 1,976.80	X
TAIL LAMP ASSY	broken	2	\$ 1,129.20	\$ 2,258.40	✓
TAIL LAMP SIDE COVER	distorted	2	\$ 80.10	\$ 160.20	✓
TAIL LAMP QUARTER PANEL	ray	2	\$ 574.50	\$ 1,149.00	X
REAR END PANEL	src	1	\$ 1,008.40	\$ 1,008.40	✓
REAR END PANEL GARNISH	defined	1	\$ 346.20	\$ 346.20	✓
SMART ANTENNA SENSOR	broken HH	1	\$ 310.60	\$ 310.60	HH X
REAR SPARE TYRE PANEL	ray	1	\$ 1,538.30	\$ 1,538.30	X
REAR SPARE TYRE TOP COVER	crumpled	1	\$ 617.10	\$ 617.10	✓
REAR FIBER TOOL BOX TRIM	HH	1	\$ 358.40	\$ 358.40	X
REAR EXHAUST BOX	HH	1	\$ 2,199.60	\$ 2,199.60	X
REAR EXHAUST PIPE HANGER	HH	2	\$ 68.10	\$ 136.20	X
REAR EXHAUST PIPE INSULATOR	1st	1	\$ 223.20	\$ 223.20	✓
REAR FENDER ARCH GARNISH	HH	2	\$ 245.88	\$ 491.77	X
REAR FENDER TRIMBOARD (LH/RH)	HH	2	\$ 387.80	\$ 775.60	✓
REAR BLIND SPORT MONITOR	HH	2	\$ 2,872.70	\$ 5,745.40	X
SUB TOTAL		17,199.38		\$ 36,171.13	
LESS 20% 25%		12,899.53		\$ 7,234.23	
DISCOUNTED TOTAL				\$ 28,936.91	
REVERSE CAMERA ASSY	HH	SN 1	\$ 536.37	\$ 536.37	X
REAR WINDSCREEN SEALANT	HH	SN 1	\$ 64.93	\$ 64.93	40/-
REAR NO. PLATE WITH COVER	broken	SN 1	\$ 63.52	\$ 63.52	45/-
REAR TRUNK LID APPS STICKER	HH	SN 1	\$ 56.46	\$ 56.46	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER	HH	SN 1	\$ 84.69	\$ 84.69	✓
REAR BUMPER RUBBER MAT	HH	SN 1	\$ 70.58	\$ 70.58	50/-
SUB TOTAL		276.15		\$ 876.54	
Labour Charge					
Panel Beating		1	\$2,000.00	\$ 2,000.00	1200/-
Spray Painting Charge		1	\$1,600.00	\$ 1,600.00	1000/-
Wiring Charge		1	\$180.00	\$ 180.00	30/-
Tuff Kote		1	\$160.00	\$ 160.00	40/-
Towing Charge		1	\$80.00	\$ 80.00	HH
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$ 150.00	80/-
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$ 120.00	80/-

Remove/Refix Exhaust Pipe	1	\$80.00	\$ 80.00	11
Front Chassis Alignment Charge	1	\$220.00	\$ 220.00	11
Diagnostic & Resetting ADAS OPTICAL SENSOR	1	\$550.00	\$ 550.00	11
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$ 550.00	11
TOTAL LABOUR		2430.00	\$ 5,690.00	
ESTIMATE TOTAL			\$ 35,503.45	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

10/12/2024 @ 1030u

N/A Actual

P/P.A.

9 days.



LKK Auto




Photo after
repair
with damaged
parts.

15,605.68

4/5 14,000/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHD6805P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI HATCHBACK(AT)(2WD)
Primary Colour:	Blue
Manufacturing Year:	2023
Engine No.:	2ZR2Y84889
Chassis No.:	JTDAE3AU303004860
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$28,006.00
Original Registration Date:	28 Jun 2024
First Registration Date:	28 Jun 2024
Transfer Count:	0
Actual ARF Paid:	\$23,709.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2032
PARF Rebate Amount:	\$17,781.00

Intended COE Rebate Details

COE Expiry Date:	27 Jun 2032
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	8
PQP Paid:	\$71,708.00
COE Rebate Amount:	\$67,151.00
Total Rebate Amount:	\$84,932.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Dec 2024

OK