



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24120104/Enh3e2(N) Date: 05/02/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	CB 7530U	Veh. Inspected	SJY 7922T
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS24/0871	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	09/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X5	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WBAZV42050LL57375	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/40 R20	BRIDGESTONE	6 mm
	L/H Front Tyre	275/40 R20	BRIDGESTONE	6 mm
	R/H Rear Tyre	275/40 R20	BRIDGESTONE	6 mm
	L/H Rear Tyre	275/40 R20	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/12/2024	Inspection Date	09/12/2024
	Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)REGISTRATION DATE: 01 OCT 2010 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	