

Certification for Bus Repairs



CBR REF NO. : SL20230469

Depot : SL

Report No.: AR-2023-0204

BUS VEHICLE NO. : SG5476R

Driver's Co no. & Name : 53566 Ng Kim Wei S/O Ng Pin

Accident Date : 11/01/2023

Date in : 11/01/2023

Date Out : 16/01/2023

Yr Of Reg	Make / Model	Chassis No.
2017	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P920HA182462

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
TOTAL FOR PARTS			SS -
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	SS	188.00
2	Contractor's repair charges	SS	650.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			SS 838.00
Repair cost of Advertisement / Livery		SS	-
TOTAL DAMAGE			SS 838.00

Certification for Bus Repairs

CBR REF NO. : SL20230469Depot : SLReport No.: AR-2023-0204BUS VEHICLE NO. : SG5476RDriver's Co no. & Name : 53566 Ng Kim Wei S/O Ng PinAccident Date : 11/01/2023Date in : 11/01/2023Date Out : 16/01/2023

Yr Of Reg	Make / Model	Chassis No.
2017	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P920HA182462
TOTAL DAMAGE		SS 838.00
Overheads		SS 251.40
Towing Charges		SS -
Repair Period : 2 day(s)	Loss of Use	SS 842.62
TOTAL LOSS		SS 1932.02

Prepared By : Goh Jit MinDate : 03/02/2023

Approved By

Workshop Mgr : Gavin Khoo Quee YongDate : 03/02/2023

	Survey Fee	refer to Group Claims
TOTAL DUE		SS 1932.02

Acknowledged

By Depot Safety : Rosy YeowDate : 07/02/2023

* This is computer generated document and does not require signature