

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22/23/23/VC05/026949 Date: 09<sup>th</sup> Jul 2024

Our Ref: CS1/LPC24070008/Eqh3e2

## M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SG 5476R INSURED VEHICLE: YP 6319L

ACCIDENT DATE: 11/01/2023

We thank you for your instruction on 26/06/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SG 5476R from M/s Vicom Assessment Centre.
- b) Colour damaged vehicle photographs of SG 5476R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SG 5476R

Make & Model : Volvo B9TL 9.4L Auto Turbo ABS

Year of Registration : 2017

Chassis Number : YV3S4P920HA182462

Engine Capacity : 9364 cc



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- 2. Our finding is that the repair cost of \$1,089.40 (before GST) quoted by M/s Vicom Assessment Centre is fair & reasonable.
- 3. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.

Your Faithfully,

1

CHEN TSUE YEE Automotive Assessor



ANG BRYAN TANI Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party

who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.