

SBS Transit Ltd
205 BRADDELL ROAD
SINGAPORE 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No.	: 571990	Claim No.	: AR-2023-0204
Accident Date	: 11/01/2023	Claim Type	: THIRD PARTY
Assignment Date	: 13/01/2023	Policy No.	:
Survey Date	: 13/01/2023	Finalised Dt.:	
Survey Report Date	: 04/02/2023	Insured Veh.:	: YP6319L

VEHICLE PARTICULARS

Vehicle No.	: SG5476R	Chassis No.	: YV3S4P920HA182462
Registration Date	: 12/07/2017	Engine No.	: D9195850
Make	: VOLVO	Engine Cap.	: 9364 CC
Model	: B9TL 9.4L AUTO TURBO	Transmission	: AUTOMATIC
		Colour	: GREEN

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 358092.4		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	275/70R22.5	BRIDGESTONE	7
FRONT LH	275/70R22.5	BRIDGESTONE	7
REAR RH	275/70R22.5	BRIDGESTONE	7
REAR LH	275/70R22.5	BRIDGESTONE	7

SURVEY CONDUCTED AT

28 SOON LEE RD
SINGAPORE 628083

REMARKS

[1]Workshop Estimate : S\$ 1,089.40
[2]Our Adjustment : S\$ 1,089.40
[3]Repair Period : 2 days
[4]We have not authorised repairs. This survey was carried out on without prejudice basis.

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour & spray painting	1089.40	1089.40
TOTAL FOR LABOUR AND SPRAY PAINTING		:	<u>1089.40</u> <u>1089.40</u>


Summary

Description	Workshop Estimate (S\$)	VAC Adjstment (S\$)
TOTAL FOR SPARE PARTS	:	0.000.00
TOTAL FOR LABOUR AND SPRAY PAINTING	:	<u>1089.40</u> <u>1089.40</u>
TOTAL REPAIR COST	:	<u>1089.40</u> <u>1089.40</u>

VICOM LTD

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT
<p>At the place of inspection, we saw this vehicle sustained frontal right portion damage.</p> <p>The damages seen during our survey were headlamp panel rh, side panel (next headlamp panel) rh and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.</p> <p>We examined all the frontal right portion damages and assessed they were from a collision or impact nature.</p> <p>By cross-referencing with the e-filed report, we were satisfied the damages were consistent with the circumstances of accident as detailed.</p>
ASSESSOR'S RECOMMENDATION
<p>Sbs Transit Ltd - (Soon Lee Bus Depot) estimated a repair cost of S\$1,089.40. We adjusted it to S\$1,089.40 on a part-by-part basis.</p> <p>Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,089.40.</p> <p>The repairs would require a period of 2 working days.</p> <p>We submit our survey report for your kind attention and would add the survey was carried out to the best of our ability, knowledge and experience.</p> <div><hr data-bbox="63 1370 531 1377"/></div> <p>Favacho Patrick Gerard for VICOM Ltd</p>