



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: JASON TEA		Ref: CS/FCI24120109/Knh3m4(N) Date: 04/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4417E	Veh. Inspected	SLA 8801E
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010695MFCT	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	09/12/2024
2. Vehicle Particulars & Condition			
Make & Model	ALPINA B4 BITURBO (A)	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAPBF3200FER20050	Colour	METALLIC BLUE
Odometer	113345 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/30 ZR20	MICHELIN	9 mm
L/H Front Tyre	245/30 ZR20	MICHELIN	9 mm
R/H Rear Tyre	265/30 ZR20	MICHELIN	9 mm
L/H Rear Tyre	265/30 ZR20	MICHELIN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/12/2024	Inspection Date	09/12/2024
Survey held at	KBS MOTORSPORTS PTE LTD 160 SIN MING DRIVE, #06-09, SIN MING AUTOCITY, SINGAPORE 575722		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	