

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorized

mercus

9/12/24

a/c \$5100

the photo after repair

4 days

VEHICLE No: SMK 3733L

1PC	REAR WINDSCREEN MOULDING	new		\$110.20	✓
1PC	TAILGATE	22/1 sent	920.20	\$1,499.20	✓
1PC	TAILGATE OUTER PANEL COVER	22/1 cno	709.52	\$980.20	✓
1PC	TAILGATE 'VEZEL' EMBLEM	new		\$66.80	✓
1PC	TAILGATE REFLECTOR O/S	11		\$700.00	X
1PC	TAILGATE INNER LOCK	11		\$199.80	X
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	del/torn	300.80	\$435.00	✓
1SET	TAILGATE INNER TRIM BOARD CLIPS	11		\$50.00	X
1PC	TAILGATE WEATHERSTRIP	11		\$288.00	X
1PC	REAR BUMPER TOP	del/torn	566.40	\$980.00	✓
1PC	REAR BUMPER CENTRE	del/torn	615.20	\$870.20	✓
1PC	REAR BUMPER LOWER SILVER	torn	300.80	\$541.00	✓
1SET	REAR BUMPER CLIPS	new		\$50.00	✓
1PC	REAR BUMPER REFLECTOR O/S	11/1 cno		\$65.00	✓
1SET	REAR BUMPER CLIPS	new		\$50.00	✓
2PCS	REAR BUMPER SIDE RETAINER	del/torn		\$45.00	✓
1PC	REAR END PANEL	22	456.00	\$665.20	✓
1PC	REAR END PANEL TOP GARNISH	11		\$341.10	X
1PC	TAILLAMP O/S	cno	580.60	\$900.00	✓
1PC	TAILLAMP HOUSING PANEL O/S	11		\$700.00	X
1PC	REAR BUZZLE SENSOR	11		\$98.00	X
1PC	REAR FENDER O/S	11		\$1,483.00	X
1PC	REAR FENDER OUTER PROTECTOR O/S	del/torn	380.20	\$760.00	✓
1PC	REAR FENDER INNER TRIM BOARD O/S	11		\$790.00	X
1PC	REAR FENDER UNDER INNER CLOTH O/S	11		\$388.20	X
1PC	REAR FLOOR PANEL	11		\$1,280.00	X
1PC	REAR FLOOR INNER SIDE PANEL O/S	11		\$450.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$522.00	X
1PC	REAR EXHAUST	11		\$765.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$108.00	X
				\$16,246.90	
				LESS 20%	\$12,997.52

S. Nett

1PC	REAR WINDSCREEN SEALANT	rec	\$50.00	40 s/n
1PC	REAR WINDSCREEN INNER SEAL	rec	\$50.00	20 s/n
1PC	REAR END PANEL SEALANT	rec	\$50.00	✓ s/n
1SET	REAR BUMPER REVERSE SENSOR	malfunction	\$680.00	200 s/n
TO CEHCK WIRING			\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00	30
TO DISMANTLE & REFX REAR WINDSCREEN			\$150.00	120
TO TRANSFER TAILGATE MECHANISM			\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$120.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM			✓ \$180.00	X
TO DISMANTLE & REFIX REAR EXHAUST			✓ \$100.00	X
TO SPRAY RUST PROOFING			\$100.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,800.00	600
TO PUTTY & SPRAY PAINTING			\$1,500.00	980
TOTAL			\$18,007.52	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5216.6
202
473-28
310
1920
6403-28
212
5122