



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: TEO SWEE KEONG		Ref: CS/FCI24120116/Knh3e2(N) Date: 07/01/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 1862L	Veh. Inspected	SMH 8724X
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010692MFCT	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	09/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA CAMRY (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MR2BN3HK704001813	Colour	METALLIC GREY
Odometer	45268 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	05/12/2024	Inspection Date	10/12/2024
Survey held at	ESTEEM PERFORMANCE PTE LTD 176 SIN MING DRIVE #01-14 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	