



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 46928

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 27/06/2024

CLAIM NO. : 12526

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBH3806G
MAKE/MODEL : HON / PCX150 A

*not allowed
in
2/7/24
L/S \$1850
the 2nd. Apr 24
3 days.*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER FOOTREST LH P/N: 49600 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
2	COVER FRONT UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
3	COVER SIDE LOWER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
4	COWLING FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$162.00	162.00
5	HEADLAMP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$778.00	778.00
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	✓ Supply/Install	6.00	\$85.00	510.00
7	MIRROR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
8	MUDGUARD FRONT (WHITE) P/N: 49588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
9	SPRAY PAINT COVER SETS AND REAR BOX - (REPORTED BY MECHANIC)	✓ Spray	1.00	\$1,067.00	1,067.00

*46928 *



bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00 <i>n</i> <i>X</i>
11	STAND SIDE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 <i>n</i> <i>X</i>
12	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 <i>205/n</i> <i>n</i>
13	WINDSHIELD (GIVI) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$404.00	404.00 <i>one</i>

SUB TOTAL

\$3,453.00

GST @ 9 %

\$310.77

GRAND TOTAL (SGD)

\$3,763.77

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

p-1730
102
1557
800
2357
202
1884

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before/after repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*46928 *

bizSAFE₃