# **PREMIUM** AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** 

: ACCIDENT REPAIRS

WORKSHOP CONTACT NO : UBI ROAD 1 : 6366 2323

FAX NO

6841 1183

REFERENCE

PA/OD/0916/2024/EQ

DATE

10-Dec-24

WIP

41302

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** 

MR LOW CHIN CHYE

**ADDRESS** 

30 MARGATE ROAD

SINGAPORE 438070

**TELEPHONE** 

: HP +65 97528284

**TYPE OF CLAIM** 

OWN DAMAGE CLAIM

POLICY NO VEHICLE NO

2070148447-04

SDM 8800 P

MODEL CODE

AUDI A3 SPORTBACK 1.4 TFS

**MODEL YEAR** 

23/10/2020

ENGINE NO

CZE 866150

CHASSIS NO

WAUZZZ8V4LA084000

MILEAGE

DATE IN

ESTIMATED BY

JOHNNY BOO / ALLAN WU

ACCIDENT DATE

: 8-Dec-24

PLACE OF ACCIDENT

8C TANJONG RHU ROAD, SINGAPORE 436891

**CARPARK LOT 1** 





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8800 P

S/N	NATURE OF JOBS		ī	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N	\$	280.00	1
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	\$	1,600.00	1 (photo)
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	\$	1,600.00	(phili)
4	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	6	\$ X 50	4,900.00 ₽	3000 .
5	TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR END PANELLING, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL AND DOOR ENTRANCE.		\$ × 550	4,600.00	2475
6	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N	\$	500.00	
	SUBTOTAL LABOUR CHARGES	:	\$	13,480.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

#### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDM 8800 P

S/N	NATURE OF JOBS			ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	4	S/N	\$ 400.00	×
. 8	TO CARRY OUT DIAGNOSTIC CHECK.		S/N	\$ 292.00	/
	TOTAL LABOUR CHARGES		:	\$ 14,172.00	-





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

#### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDM 8800 P

#### **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER / BR	1	\$ 2,483.00	
2	REAR BUMPER FIXING PARTS	1	\$ 216.00	- N
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2		
		2	\$ 36.00	
4	REAR WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 96.00	
5	REAR BUMPER SPOILER	1	\$ 297.00	
6	REAR BUMPER REFLECTOR - LH	1	\$ 41.00	
7	REAR BUMPER GUIDE SECTION - LH	1	\$ 84.00	æ.
8	REAR SIDE PANEL - LH · / M	1	\$ 5,131.00	
9	REAR WHEEL HOUSING LINER - LH	1	\$ 289.00	1
10	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 67.00	
11	REAR OUTER TAIL LIGHT - LH	1	\$ 1,656.00	
12	REAR QUARTER GLASS - LH / 18 ( / / / / )	1	\$ 365.00	4
13	REAR QUARTER GLASS CHROME TRIM STRIPS - LH / nk	1	\$ 326.00	
14	REAR ROOF CHROME MOLDING - LH	1	\$ 741.00	
15	1/4 GLASS SEALANT / / 1/5	S/N	\$ 100.00	
16	METAL FILTER POWDER / /V	S/N	\$ 280.00	
17	ACRYLIC SEALANT	S/N	\$ 180.00	
18	STONE CHIP	S/N	\$ 180.00	
19	CAVITYWAX	S/N	\$ 140.00	
20	SUNDRIES		\$ 800.00	
	TOTAL SPARE PARTS	:	\$ 13,508.00	
	TOTAL LABOUR CHARGES	:	\$ 14,172.00	
	GRAND TOTAL	:	\$ 27,680.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

### **PREMIUM** AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE **AUTHORISED DATE** 

**EXCESS COST** LIABILITY

REMARKS

PLEASE NOTE

Steve CLKK) 12/12/24, 11-002L 00- NA AL EXPT -?

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF

THE AFFECTED VEHICLE. SHOULD WE REQUIRE

FURTHER LABOUR CHARGES AND SPARE PARTS IN THE

PROGRESS OF REPAIR, WE SHALL INFORM YOU

ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY. PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

JOHNNY BOO **BODY REPAIR MANAGER**  **ALLAN WU** CLAIMS CONSULTANT