

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KWOK FAH SING
BLK 490A TAMPINES ST 45 #08-199
SINGAPORE 520490

Contact : 96989442

Store (LXK)
19/12/24, 11:31 am
m n
L/S
7 days

TAX INVOICE

Repair Code : CLM18460
Date in : 14/11/2024
Vehicle Num. : CB7837K
Model : TOYOTA HIACE 2.5 M
Chassis/Eng# : KDH2000067946/2KD1576201

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER / OR	1	673.10	673.10 /
REAR BUMPER LOWER BRACKET / BT	4	48.00	192.00 ✓
REAR BUMPER SIDE RETAINER L/R / OR	2	47.00	94.00 ✓
REAR END PANEL (INNER) ? / OR	1	1283.40	994 ✓ 1,283.40
REAR END PANEL (OUTER) ? / OR	1	445.00	445.00 ✓
REAR EXHAUST GASKET ? X nn	1	48.30	48.30
REAR EXHAUST PIPE ? / local repair / BT	1	796.20	796.20 100 (SN)
REAR EXHAUST RUBBER MOUNTING ? X nn	2	52.20	104.40
REAR FLOOR PANEL CARPET ? X nn	1	680.00	680.00
REAR FLOOR PANEL TOP PLATE ? X nn	1	195.00	195.00
REAR FLOOR PANEL TOP PLATE SIDE COVER RH ? X nn	1	88.00	88.00
REAR MECHANISM LOCK COVER ? / OR	1	123.20	123.20 ✓
REAR RH TAILLAMP / OR	1	379.00	379.00 ✓
REAR RH TAILLAMP LOWER GARNISH / CRU	1	195.00	195.00 140 ✓
REAR RH TAILLAMP LOWER GARNISH RETAINER X nn	1	79.00	79.00
REAR RH TAILLAMP PANEL X R	1	570.30	570.30
REAR SPARE TYRE CARRIER ? / BT	1	379.00	379.00 243 ✓
REAR STEP PANEL ? / OR	1	175.40	175.40 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KWOK FAH SING
 BLK 490A TAMPINES ST 45 #08-199
 SINGAPORE 520490

Contact : 96989442

TAX INVOICE

Repair Code : CLM18460
 Date in : 14/11/2024
 Vehicle Num. : CB7837K
 Model : TOYOTA HIACE 2.5 M
 Chassis/Eng# : KDH2000067946/2KD1576201

REAR TAILGATE / <i>nn</i>	1	3106.80	3,106.80	2650 /
REAR TAILGATE 'LOGO' EMBLEM / <i>mc</i>	1	63.00	63.00	✓
REAR TAILGATE 'REGIUS ACE' STICKER / <i>mc</i>	1	85.00	85.00	✓
REAR TAILGATE DAMPER L/R X <i>nn</i>	2	214.00	428.00	
REAR TAILGATE HINGES L/R X <i>nn</i>	2	67.00	134.00	
REAR TAILGATE INNER LOWER SIDE MOULDING L/R X <i>nn</i>	2	17.00	34.00	
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R X <i>nn</i>	2	17.00	34.00	
REAR TAILGATE INNER TRIM BOARD ? X <i>nn</i>	1	469.00	469.00	
REAR TAILGATE LOCK STRIKER X <i>nn</i>	1	53.00	53.00	
REAR TAILGATE MECHANISM LOCK ? / <i>jamed / Bi</i>	1	264.00	264.00	✓
REAR TAILGATE OUTER GARNISH X <i>nn</i>	1	151.20	151.20	
REAR TAILGATE WEATHER STRIP ? / <i>TN</i>	1	391.00	391.00	✓
Subtotal before discount		7011.70	11,713.30	
Percentage discount 25%		-25%	2,928.33	
Sub-total 1		5258.77	8,784.98	
REAR BUMPER CLIPS - SET / <i>mc</i>	1	80.00	80.00	30
REAR BUMPER REVERSE SENSOR - SET / <i>BR</i>	1	280.00	280.00	200
REAR RH TAILLAMP LOWER GARNISH CLIPS - SET / <i>mc</i>	1	20.00	20.00	10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KWOK FAH SING
BLK 490A TAMPINES ST 45 #08-199
SINGAPORE 520490

Contact : 96989442

TAX INVOICE

Repair Code : CLM18460

Date in : 14/11/2024

Vehicle Num. : CB7837K

Model : TOYOTA HIACE 2.5 M

Chassis/Eng# : KDH2000067946/2KD1576201

REAR TAILGATE '60KM' STICKER	✓ MK	1	25.00	25.00	29
REAR TAILGATE 'AWC' STICKER	✓ MK	1	25.00	25.00	21
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	! X nn	1	50.00	50.00	
REAR TAILGATE WINDSCREEN SEAL	X nn	1	80.00	80.00	
REAR TAILGATE WINDSCREEN SEALANT	✓ MK	1	80.00	80.00	40
Subtotal before discount			320	640.00	
Percentage discount 0%				0.00	
Sub-total 2				640.00	
Parts-total				9,424.98	

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

30 80.00

To remove, reinstall tailgate windscreen

120 150.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

X ? 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

400 1,100.00 550

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

X ? 100.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400 1,000.00 800

To apply anti-rust chemical on repaired and replaced panel.

30 150.00

To remove, reinstall tailgate mechanism and check for function

50 80.00

Labour Total 1580

2,760.00

Parts & Labour Total

12,184.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Computer-generated document which requires no signature.***

page 3

7158.77

L/S - 5727.02
= 5700