



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24120123/Evh3e2
75 BRAS BASAH ROAD	Date:	18/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 5859R	Veh. Inspected	SNA 960H
Policy No.	-	Coverage	0
Claim No.	MT/1305144-002	Excess	\$0.00
Assign From	HELENA TAN	Assign Date	10/12/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH	C.C	1797
Engine No.	2ZR2L53230	Year of Reg.	01/06/2021
Chassis No.	ZWR800487522	Colour	WHITE
Odometer	163959 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	YOKOHAMA	5
L/H Front Tyre	205/55 R16	YOKOHAMA	5
R/H Rear Tyre	205/55 R16	YOKOHAMA	5
L/H Rear Tyre	205/55 R16	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2024	Inspection Date	10/12/2024 (11:21)
Survey held at	N-51 AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days